



DESIGNATED ORIGINAL

Certified By MDP

Public Service Electric and Gas Company P.O. Box E Hancocks Bridge, New Jersey 08038

Salem Generating Station

October 6, 1982 50-311

Mr. R. C. Haynes  
Regional Administrator  
USNRC  
Region 1  
631 Park Avenue  
King of Prussia, Pennsylvania 19406

Dear Mr. Haynes:

REPORTABLE OCCURRENCE 82-113/01P  
SALEM NO. 2 UNIT LER

This letter is to confirm our verbal report to the NRC Headquarters on Tuesday, October 5, 1982, advising of a potential reportable occurrence in accordance with IE Bulletin 80-24.

During routine power operation, a service water leak was discovered inside the Containment Building, on No. 22 Containment Fan Coil Unit. The leak rate was approximately 0.5 gallons per minute, and the leak has been isolated.

An investigation is in progress, and a detailed report will be submitted in the time period specified by IE Bulletin 80-24.

Sincerely yours,

H. J. Midura  
General Manager -  
Salem Operations

RF:ks

CC: Distribution

8210080241 821006  
PDR ADDCK 05000311  
S PDR

The Energy People

IE29