



LOUISIANA
POWER & LIGHT


142 DELARONDE STREET
P. O. BOX 6008 • NEW ORLEANS, LOUISIANA 70174 • (504) 366-2345

May 26, 1983

W3I83-0193
Q-3-A35.07.42

Mr. John T. Collins, Regional Administrator, Region IV
U. S. Nuclear Regulatory Commission
611 Ryan Plaza Drive, Suite 1000
Arlington, Texas 76012

SUBJECT: Waterford SES Unit No. 3
Docket No. 50-382
Significant Construction Deficiency No. 42 R-1
"HMA Auxiliary Relays"



REFERENCE: LP&L letter W3I83-0100 dated March 28, 1983

Dear Mr. Collins:

The above referenced letter indicated submittal of a Final Report to the USNRC no later than May 27, 1983.

At the present time, NCR W3-3361 is redispositioned to use the heat shrink tubing available on site. The corrective action is underway and should be completed by June 20, 1983.

Therefore, a Final Report will be submitted to the USNRC by July 17, 1983.

Very truly yours,

F. J. Drummond
Project Support Manager - Nuclear

FJD/RWP/MAL:keh

- | | |
|--|------------------------|
| cc: 1) Director
Office of Inspection & Enforcement
U. S. Nuclear Regulatory Commission
Washington, D. C. 20555 | 3) Mr. E. L. Blake |
| 2) Director
Office of Management
Information and Program Control
U. S. Nuclear Regulatory Commission
Washington, D. C. 20555 | 4) Mr. W. M. Stevenson |

8306070274 830526
PDR ADOCK 05000382
S PDR

IE-27
110