

CONTROL BLOCK:

--	--	--	--	--	--

1

0	1	P	A	B	V	S	1	2	0	0	-	0	0	0	0	-	0	0	3	4	1	1	1	1	4			5	
3		9						14						25						30						57		58	
		LICENSEE CODE												LICENSE NUMBER															

REPORT SOURCE: 0 1 8

DOCKET NUMBER: 6 0 5 0 0 0 3 3 4 7

EVENT DATE: 0 9 2 5 8 2 3

REPORT DATE: 1 0 2 1 8 2 9

02 | During an attempt to secure the turbine driven aux feed pump [FW-P-2]

03 | following a reactor trip, TV-MS-105B failed to close. FW-P-2 was

04 secured by MOV-MS-105 (Technical Specification 3.7.1.2). Due to the

05 operability of the two motor driven auxiliary feed pumps, there were no

06 safety implications involved. Previous similar events include LER 82-33

07 and LER 79-7.

0 3 |

7 8 9

0 9

SYSTEM CODE C C 11

CAUSE CODE X 12

CAUSE SUBCODE Z 13

COMPONENT CODE V A L V E X 14

COMP. SUBCODE F 15

VALVE SUBCODE D 16

(17) LER/RO REPORT NUMBER EVENT YEAR SEQUENTIAL REPORT NO. CODE TYPE NO.

8	2	—	0	3	8	0	3	L	—	0
21	22	23	24	25	26	27	28	29	30	31

ACTION TAKEN		FUTURE ACTION		EFFECT ON PLANT		SHUTDOWN METHOD		HOURS				ATTACHMENT SUBMITTED		NPRD-4 FORM SUB.		PRIME COMP. SUPPLIER		COMPONENT MANUFACTURER			
X	18	X	19	Z	20	Z	21	0	0	0	0	Y	23	N	24	A	25	M	1	2	0
33	34	35	36	37	38	39	40	41	42	43	44	45	46	47	48	49	50	51	52	53	54

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

1	0	Apparently, MS-20, a check valve upstream of TV-MS-105B failed resulting
---	---	--

11 in a nut lodging in TV-MS-105B valve body. The nut was removed and the

valve and pump were returned to service. MS-20 will be repaired at the

1	2
---	---

 | next available outage.

[illegible]

FACILITY STATUS		% POWER			OTHER STATUS		METHOD OF DISCOVERY		DISCOVERY DESCRIPTION		
G	28	0	0	0	29	N/A	30	A	31	Operator Observation	32
9		10		12			44	45		46	

ACTIVITY CONTENT
RELEASED OF RELEASE AMOUNT OF ACTIVITY (35) LOCATION OF RELEASE (36)
[] [Z] (33) [Z] (34) N/A N/A

PERSONNEL EXPOSURES									
NUMBER			TYPE	DESCRIPTION					
0	0	0	(37) Z	(38) N/A	8211020479	821021			
					PDR	ADQCK	05000	334	
					S				

PERSONNEL INJURIES				PDR
NUMBER	DESCRIPTION			
0 0 0 (40)	N/A			

LOSS OF OR DAMAGE TO FACILITY		(43)
TYPE	DESCRIPTION	
Z (42)	N/A	

PUBLICITY			NRC USE ONLY
ISSUED	DESCRIPTION	(45)	
[N]	(44)	N/A	

NRC USE ONLY

076-11

Attachment To LER 82-038/03L
Beaver Valley Power Station
Duquesne Light Company
Docket No. 50-334

No further information is available or needed to satisfy the reporting requirement.