

UNIT SHUTDOWNS AND POWER REDUCTIONS

REPORT MONTH September 1982

DOCKET NO. 50-301
UNIT NAME Point Beach Unit '2
DATE October 4, 1982
COMPLETED BY C. W. Fay
TELEPHONE 414/277-2811

No.	Date	Type ¹	Duration (Hours)	Reason ²	Method of Shutting Down Reactor ³	Licensee Event Report No.	System Code ⁴	Component Code	Cause and Corrective Action To Prevent Recurrence
5	820925	S	142.8	B	1	N/A	CB	PUMPPX	No. 2 seal on "B" reactor coolant pump exhibited signs of increased degradation and was replaced.

¹ F: Forced
S: Scheduled

² Reason:
A- Equipment Failure (explain)
B- Maintenance or Test
C- Refueling
D- Regulatory Restriction
E- Operator Training & License Exam
F- Administrative
G- Operational Error (explain)
H- Other (explain)

³ Method:
1- Manual
2- Manual Scram
3- Automatic Scram
4- Other (explain)

⁴ Exhibit G-Instructions for Preparation of Data Entry Sheets for LER File (NUREG-0161)

⁵ Exhibit I- Same Source