




KANSAS GAS AND ELECTRIC COMPANY

GLENN L. KOESTER
VICE PRESIDENT - NUCLEAR

June 1, 1983

Mr. W.C. Seidle, Chief
Reactor Projects Branch 2
U.S. Nuclear Regulatory Commission
Region IV
611 Ryan Plaza Drive, Suite 1000
Arlington, Texas 76011



KMLNRC 83-062

Re: Docket No. STN 50-482

- Ref: 1) Interim Report KMLNRC 82-199 dated 5/14/82
from GLKoester, KG&E, to WCSeidle, NRC
2) Interim Report KMLNRC 82-241 dated 9/9/82
from GLKoester, KG&E, to WCSeidle, NRC
3) Interim Report KMLNRC 82-260 dated 12/13/82
from GLKoester, KG&E, to WCSeidle, NRC

Subj: Interim 10CFR50.55(e) Report - Inadequate Material
Control for Special Scope Items

Dear Mr. Seidle:

This letter provides an interim 10CFR50.55(e) report on inadequate material control for special scope items as described in Reference 1). Additional information concerning this subject was also included in Reference 2) and Reference 3).

The investigation and evaluation of this concern is nearing completion. The results of numerous inspections, tests and document reviews have been tabulated and should be sent to the Architect/Engineer within the next two weeks for final evaluation of this concern.

A final or interim report on this subject will be submitted on or before September 1, 1983. In the interim, please direct any questions concerning this subject to me or to Mr. Otto Maynard of my staff.

Yours very truly,

Glenn L. Koester

GLK:bb

cc: RCDeYoung
HRoberts/WSchum

8306090231 830601
PDR ADOCK 05000482
S PDR

1E-27

1/0