



Commonwealth Edison

One First National Plaza, Chicago, Illinois
Address Reply to: Post Office Box 767
Chicago, Illinois 60690

June 1, 1983

Mr. James G. Keppler, Regional Administrator
- Region III
U.S. Nuclear Regulatory Commission
799 Roosevelt Road
Glen Ellyn, IL 60137

Subject: Byron Station Units 1 and 2
DC Cable Failure
NRC Docket Nos. 50-454 and 50-455

Reference (a): December 6, 1982 letter from T. R.
Tramm to J. G. Keppler.

Dear Mr. Keppler:

Reference (a) provided an interim report on deficiency number 82-07 reportable pursuant to 10 CFR 50.55(e) regarding the failure of several DC cables in an underground duct at Byron. A final report was expected to be available by April 1, 1983. It now appears that the final report will not be ready until sometime in September, 1983.

Please address any questions regarding this matter to this office.

Very truly yours,

T. R. Tramm
Nuclear Licensing Administrator

lm

6680N

8306100178 830601
PDR ADOCK 05000454
S PDR

IE27
1/0

JUN 3 1983