




**GULF STATES UTILITIES COMPANY**

POST OFFICE BOX 2951 • BEAUMONT, TEXAS 77704

AREA CODE 713 838-6631

January 13, 1983  
RBG-14,124  
File Nos. G9.5, G9.25.1.1

Mr. John T. Collins, Regional Administrator  
U. S. Nuclear Regulatory Commission  
Region IV, Office of Inspection and Enforcement  
611 Ryan Plaza Drive, Suite 1000  
Arlington, Texas 76011



Dear Mr. Collins:

River Bend Station Unit 1  
Docket No. 50-458  
Interim Report/DR-86

On December 13, 1982, Gulf States Utilities Company (GSU) notified the Nuclear Regulatory Commission's Region IV Office of a condition potentially reportable under 10CFR50.55(e) concerning the possible misinterpretation of an electrical equipment hold down weld detail (DR-86). GSU has not completed its evaluation at this time. An interim or final status report will be submitted by March 8, 1983.

Sincerely,

J. E. Booker  
Manager-Engineering,  
Nuclear Fuels & Licensing  
River Bend Nuclear Group

JEB/PJD/kt

cc: Director of Inspection & Enforcement  
U. S. Nuclear Regulatory Commission  
Washington, D. C. 20555

R. L. Brown (SRI)

8301250113 830113  
PDR ALOCK 05000458  
S PDR

TE 27