



GULF STATES UTILITIES COMPANY

POST OFFICE BOX 2951 • BEAUMONT, TEXAS 77704

AREA CODE 713 838-6631

June 3, 1983

RBG- 15,181

File Nos. G9.5, G9.25.1.1

Mr. John T. Collins, Regional Administrator
U. S. Nuclear Regulatory Commission
Region IV, Office of Inspection and Enforcement
611 Ryan Plaza Drive, Suite 1000
Arlington, Texas 76011

Dear Mr. Collins:

River Bend Station Unit 1
Docket No. 50-458
Final Report/DR-71



On August 27, 1982, Gulf States Utilities Company (GSU) notified Region IV of a condition potentially reportable under 10CFR50.55(e) concerning inconsistencies found in the QA program at the W. J. Woolley Company, the manufacturer of personnel air locks at River Bend Station (DR-71). GSU subsequently issued Interim Reports dated September 27, 1982, January 14, 1983, and April 19, 1983.

GSU has completed its evaluation and determined that DR-71 does not meet the reporting requirements of 10CFR50.55(e) in that no physical hardware changes were required. W. J. Woolley Company has taken the necessary actions to correct the inconsistencies of their QA program. This completes GSU's response on this matter.

Sincerely,

J. E. Bocker
Manager-Engineering,
Nuclear Fuels & Licensing
River Bend Nuclear Group

JEB/PJD/kt

cc: Director of Inspection & Enforcement
U. S. Nuclear Regulatory Commission
Washington, D. C. 20555

R. L. Brown (SRI)

8306130317 830603
PDR ADQCK 05000458
S PDR

IE-27
110