

**GULF STATES UTILITIES COMPANY**

POST OFFICE BOX 2951 • BEAUMONT, TEXAS 77704

AREA CODE 713 838-6631

June 18, 1982

RBG- 12,860

File Nos. G9.5, G9.25.1.1

Mr. John T. Collins, Regional Administrator  
U. S. Nuclear Regulatory Commission  
Region IV, Office of Inspection and Enforcement  
611 Ryan Plaza Drive, Suite 1000  
Arlington, Texas 76011

Dear Mr. Collins:

River Bend Station Unit 1  
Docket No. 50-458  
Final Report/DR-53

On May 24, 1982, Gulf States Utilities Company (GSU) notified the Nuclear Regulatory Commission's Region IV Office of a condition potentially reportable under 10CFR50.55(e) concerning B. F. Shaw rolled plate pipe rejected for incomplete documentation and radiographs (DR-53). GSU has completed its review and determined that the deficiency is not reportable under 10CFR50.55(e). This concludes GSU's response on this subject.

Sincerely,

*J E Booker*

J. E. Booker  
Manager-Engineering & Licensing  
River Bend Nuclear Group

*WLB/CJK*  
JEB/RSK/kt

cc: Director of Inspection & Enforcement  
U. S. Nuclear Regulatory Commission  
Washington, D. C. 20555

IE-27

*III*

JUN 4 1982

8303080362 820618  
PDR ADOCK 05000458  
S PDR

DESIGNATED ORIGINAL

Certified By *cu*