




Public Service Company of Colorado

2420 W. 26th Avenue, Suite 100D Denver, Colorado 80211

~~11/10~~ H00S

1/0

June 8, 1983
Fort St. Vrain
Unit No. 1
P-83206



Mr. John T. Collins, Regional Administrator
Region IV
Nuclear Regulatory Commission
611 Ryan Plaza Drive
Suite 1000
Arlington, Texas 76011

DOCKET NO. 50-267

SUBJECT: Open Item (267/7815-01)

REFERENCES: 1) NRC letter G-78105; G.L. Madsen
to C.K. Millen dated 11/8/78

2) NRC letter G-83205; G.L. Madsen
to O.R. Lee, dated 5/23/83

Dear Mr. Collins:


Open Item (267/7815-01) initially reported in IE Inspection Report 50-267/78-15, Reference (1), was reidentified as being unresolved in IE Inspection Report 50-267/83-06, Reference (2), pending:

1. Analysis of the radiological hazards involved in using the reactor building sump as a part of the radwaste system.
2. Provide for proper monitoring of the effluent released from the sump which includes the collection of representative effluent samples.
3. Revision to the FSV FSAR by July 1, 1983, to include the reactor building sump as a part of the radwaste system.

The purpose of this letter is to clarify PSC's proposed resolution to item 3. PSC intends to include the FSAR revision required to resolve item 3 in the next scheduled FSAR update, which is scheduled to be

submitted to the NRC, per 10CFR50.71(e), by July 22, 1983. PSC requests that the commitment date for item 3 be changed from July 1 to August 1, 1983, to reflect the required annual FSAR Update submittal deadline. PSC will proceed under this FSAR Update schedule for item 3 above, along with the entire annual FSV FSAR Update, unless you specify otherwise.

Very truly yours,

A handwritten signature in cursive script, appearing to read "Lawrence Brey".

H. L. Brey, Manager
Nuclear Engineering Division

HLB/MAJ:pa