

LICENSEE EVENT REPORT

CONTROL BLOCK: 1

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

01 M I I D I C I C I 1 2 0 0 0 - 0 0 0 0 0 0 - 0 0 0 3 4 1 1 1 1 1 4 5

LICENSEE CODE LICENSE NUMBER LICENSE TYPE CAT 58

CON'T 01 L 6 0 5 0 0 0 3 1 5 7 0 5 1 2 8 3 8 0 6 0 6 8 3 9

REPORT SOURCE DOCKET NUMBER EVENT DATE REPORT DATE

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES 10

02 DURING A SURVEILLANCE TEST ON THE PRESSURIZER PRESSURE PROTECTION SET III, IT WAS

03 FOUND THAT THE HIGH PRESSURE REACTOR TRIP BISTABLE WOULD NOT TRIP. THIS EVENT WAS

04 NON-CONSERVATIVE WITH RESPECT TO TECHNICAL SPECIFICATION 3.3.1.1 TABLE 3.3-1 ITEM 10.

05 THE ACTION REQUIREMENTS WERE MET. PUBLIC HEALTH AND SAFETY WERE NOT AFFECTED. THIS

06 IS THE FIRST OCCURRENCE OF THIS TYPE.

07

08

09 I I A 11 E 12 E 13 I I N S I T I R U 14 S 15 Z 16

SYSTEM CODE CAUSE CODE CAUSE SUBCODE COMPONENT CODE COMP. SUBCODE VALVE SUBCODE

17 8 3 1 0 4 2 1 0 3 L 1 0

LER/RO REPORT NUMBER EVENT YEAR SEQUENTIAL REPORT NO. OCCURRENCE CODE REPORT TYPE REVISION NO.

18 A 13 Z 19 Z 20 Z 21 0 0 0 0 22 N 23 Y 24 N 25 F 1 8 0 26

ACTION TAKEN FUTURE ACTION EFFECT ON PLANT SHUTDOWN METHOD HOURS ATTACHMENT SUBMITTED NPD-4 FORM SUB. PRIME COMP. SUPPLIER COMPONENT MANUFACTURER

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS 27

10 INVESTIGATION REVEALED THAT THE HIGH PRESSURE REACTOR TRIP BISTABLE, MANUFACTURED BY

11 FOXBORO COMPANY HAD FAILED. THE BISTABLE WAS REPLACED, CALIBRATED, VERIFIED TO BE

12 OPERATING CORRECTLY AND RETURNED TO SERVICE.

13

14

15 E 28 1 0 0 0 29 NA 30 B 31 SURVEILLANCE TEST 32

FACILITY STATUS % POWER OTHER STATUS METHOD OF DISCOVERY DISCOVERY DESCRIPTION

16 Z 33 Z 34 NA 35 NA 36

RELEASED OF RELEASE AMOUNT OF ACTIVITY LOCATION OF RELEASE

17 0 0 0 37 Z 38 NA 39

PERSONNEL EXPOSURES TYPE DESCRIPTION

18 0 0 0 40 NA 41

PERSONNEL INJURIES DESCRIPTION

19 Z 42 NA 43

LOSS OF OR DAMAGE TO FACILITY TYPE DESCRIPTION

20 N 44 NA 45

PUBICITY DESCRIPTION

8306210142 830606
PDR ADOCK 05000315
S PDR

NAME OF PREPARER R. A. PALMER

PHONE (616) 465-5901

NRC USE ONLY

50 61 7-026