



Tennessee Valley Authority, Post Office Box 2000, Soddy-Daisy, Tennessee 37379-2000

Ken Powers
Vice President, Sequoyah Nuclear Plant

August 10, 1994

U.S. Nuclear Regulatory Commission
ATTN: Document Control Desk
Washington, D.C. 20555

Gentlemen:

| | | |
|----------------------------|---|--------------------|
| In the Matter of |) | Docket Nos. 50-327 |
| Tennessee Valley Authority |) | 50-328 |

SEQUOYAH NUCLEAR PLANT (SQN) - INSPECTION REPORT NOS. 50-327, 328/94-06 -
EXTEND CORRECTIVE ACTION DUE DATE

Reference: Letter from Ken Powers to NRC dated April 8, 1994, "Sequoyah
Nuclear Plant (SQN) - NRC Inspection Report Nos. 50-327,
328/94-06 - Reply to Notice of Violation (NOV) 50-327,
328/94-06-01"

This letter provides details concerning an extension to the due date for the corrective action to be taken in response to the referenced violation. The corrective action being extended involves revision to the environmental qualification (EQ) binders associated with cables in the steam generator enclosures. Since the time of the response to the violation, it has been determined that additional EQ binders are required to be revised. Additionally, many of these same EQ binders are scheduled to be revised to address other unrelated issues. Multiple revisions to the same binders will not be as cost effective as revising the binders in a single revision. Therefore, it is prudent to extend the commitment schedule. The enclosure includes the commitment and revised due date.

If you have any questions concerning this submittal, please telephone J. W. Proffitt at (615) 843-6651.

Sincerely,

Ken Powers

cc: See page 2

160072

9408180190 940810
PDR ADOCK 05000327
G PDR

IEO1
11

U.S. Nuclear Regulatory Commission

Page 2

August 10, 1994

cc: Mr. D. E. LaBarge, Project Manager
U.S. Nuclear Regulatory Commission
One White Flint, North
11555 Rockville Pike
Rockville, Maryland 20852-2739

NRC Resident Inspector
Sequoyah Nuclear Plant
2600 Igou Ferry Road
Soddy-Daisy, Tennessee 37379-3624

Regional Administrator
U.S. Nuclear Regulatory Commission
Region II
101 Marietta Street, NW, Suite 2900
Atlanta, Georgia 30323-2711

ENCLOSURE

COMMITMENTS
INSPECTION REPORT 94-06

The EQ binders will be revised to reflect the correct environmental conditions and to establish the new qualified life for the affected components. This action will be completed by February 10, 1995.