

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

CON'T

0	1
---	---

2 8

REPORT SOURCE

L	6	0	5	0	0	0	3	2	8	7	0	2	0	2	8	3	8	0	3	0	2	8	3	9
---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---

60 61 68 69 74 75 80

DICTIONARY NUMBER EVENT DATE REPORT DATE

0 2 | With unit 2 in mode 1 (98% power) at 0030 CST on 02/02/83, one containment sump
0 3 | level channel 2-LT-63-176 was declared inoperable due to failing high. A similar
0 4 | event occurred at 1950 CST on 02/02/83. Both events required entry into action
e 5 | statement 18 of LCO 3.3.2. There was no effect upon public health and safety.
0 6 | Previous occurrences - eight (SQRO-50-327/82070, 81009, 81155, 82026, 81151, 80091,
0 7 | 81040, and 81116).

0	8																	
7	8	9																
SYSTEM CODE			CAUSE CODE		CAUSE SUBCODE		COMPONENT CODE				COMP. SUBCODE		VALVE SUBCODE					
I B (11)			E (12)		E (13)		I N S T R U (14)				T (15)		Z (16)					
9 10			11 12		12 13		13 18				19 20		20					
EVENT YEAR			SEQUENTIAL REPORT NO.		OCCURRENCE CODE		REPORT TYPE		REVISION NO.									
8 3 (17)			0 1 5 (18)		0 3 (19)		L (20)		0 (21)									
21 22			23 24		24 26		27 28		29 30		31 32							
ACTION TAKEN			FUTURE ACTION		EFFECT ON PLANT		SHUTDOWN METHOD		HOURS		ATTACHMENT SUBMITTED		NPRD-4 FORM SUB.		PRIME COMP. SUPPLIER		COMPONENT MANUFACTURER	
E (18) X (19)			Z (20)		Z (21)		0 0 0 0 (22)		N (23)		N (24)		L (25)		B 0 8 0 (26)			
33 34			35 36		36 37		37 40		41 42		42 43		43 44		44 45			

1 0 The level channel was found deviating from the other three channels and troubleshooting

1 1 indicates that most probably an air bubble existed in the oil-filled reference sense

1 2 line from the bellows to the transmitter. The channel was recalibrated after each event

1 3 and returned to service on 02/02/83. On 02/12/83, the channel was removed from service

1 4 and the sense line refilled and calibrated. Since that time, no problems have been

1 5 noted and no further action is planned.

FACILITY STATUS (1) 5 (E) (28) % POWER (0) 9 (8) (29) OTHER STATUS (30) NA
 METHOD OF DISCOVERY (B) (31) Operator observation (32) DISCOVERY DESCRIPTION
 ACTIVITY CONTENT (1) 6 (Z) (33) (Z) (34) AMOUNT OF ACTIVITY (35) NA LOCATION OF RELEASE (36)
 PERSONNEL EXPOSURES (1) 7 (0) 0 0 (37) (Z) (38) NA
 PERSONNEL INJURIES (1) 8 (0) 0 0 (40) NA
 LOSS OF OR DAMAGE TO FACILITY (1) 9 (Z) (42) NA
 PUBLICITY (2) 0 (N) (44) 8303210321 830302 PDR A/D/CK 05000328 PDR
 NRC USE ONLY