

**Commonwealth Edison**

One First National Plaza, Chicago, Illinois  
 Address Reply to: Post Office Box 767  
 Chicago, Illinois 60690

June 2, 1983

*enc  
 +1*

PRINCIPAL STAFF			
✓ RA	<i>Lee</i>	ENF	
D/RA		SCS	
A/RA		PAO	
✓ PRP		SLO	
DRMA		RC	
URMSP			
DE			
EL			
OL		FILE	<i>Lee</i>

Mr. James G. Keppler, Regional Administrator  
 - Region III  
 U.S. Nuclear Regulatory Commission  
 799 Roosevelt Road  
 Glen Ellyn, IL 60137

Subject: Byron Station Units 1 and 2  
 Cable Tray Stiffeners Weld Quality  
NRC Docket Nos. 50-454 and 50-455

References (a): July 9, 1982 letter from C. E.  
 Norelius to Cordell Reed.

(b): June 25, 1981 letter from J. S. Abel  
 to J. G. Keppler.

Dear Mr. Keppler:

This letter will provide the notification requested in reference (a) regarding amendment of the Byron/Braidwood FSAR regarding cable tray weld inspection criteria. This change was promised in reference (b).

Amendment 41 to the Byron/Braidwood FSAR provided a revision to page 3.10-6 which indicates the criteria used for inspection of cable tray welds.

Please address further questions regarding this matter to this office.

Very truly yours,

*F. H. Lentine*

*T. R. Tramm*  
 Nuclear Licensing Administrator

lm

6693N

JUN 6 1983

*Lee  
 1/0*