

LICENSEE EVENT REPORT

Page 1 of 1

CONTROL BLOCK:

--	--	--	--	--	--	--

 ①

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

0	1	M				S	G	G	S	1	2	0	0	0	0	0	0	0	0	0	0	3	4	1	1	1	1	4	5								
7	8	LICENSEE CODE										14	LICENSE NUMBER										25	LICENSE TYPE										30	57 CAT 58		

CON'T

0	1
---	---

REPORT SOURCE

L	6	0	5	0	0	0	4	1	6	7	0	1	3	1	8	3	8	0	3	0	1	8	3	9
---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---

DOCKET NUMBER

EVENT DATE

REPORT DATE

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

0 2 | On January 31, 1983, smoke detectors for the Upper Cable Spreading Room in the
0 3 | Control Building (Zone 1-23) alarmed and would not reset. This resulted in entering
0 4 | the action statements for T.S.3.3.7.9 and is being reported pursuant to T.S.
0 5 | 6.9.1.13.b. The event had no effect on the health and safety of the public and did
0 6 | not constitute a threat to plant safety.

0 7 0 8 7 8 0 80

09		SYSTEM CODE A B		CAUSE CODE X		CAUSE SUBCODE Z		COMPONENT CODE I N S T R U				COMP. SUBCODE E		VALVE SUBCODE Z	
7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22
LER/RO REPORT NUMBER		EVENT YEAR 8 3		SEQUENTIAL REPORT NO. 0 4 3		OCCURRENCE CODE 0 3		REPORT TYPE L		REVISION NO. 0		ACTION TAKEN X		FUTURE ACTION Z	
23	24	25	26	27	28	29	30	31	32	33	34	35	36	37	38
EFFECT ON PLANT Z		SHUTDOWN METHOD Z		HOURS 0 0 0		ATTACHMENT SUBMITTED N		NPRD-4 FORM SUB. N		PRIME COMP. SUPPLIER A		COMPONENT MANUFACTURER H 2 6 0			
39	40	41	42	43	44	45	46	47	48	49	50	51	52		

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

1 0 | The cause was indeterminable although it is suspected that dust in a detector caused
1 1 | it to alarm. Upon investigation, under a maintenance work order, no problem was
1 2 | found. The detector was then cleaned, functionally tested, and returned to service.
1 3 | No further action is required. This is a final report.

1 4 7 8 9 80

FACILITY STATUS (28) 1 5 G 28 0 0 0 29 13 OTHER STATUS (30) NA 44 METHOD OF DISCOVERY (31) A 31 46 DISCOVERY DESCRIPTION (32) Alarmed Condition 80

ACTIVITY CONTENT
RELEASED OF RELEASE

1 6 7 33 10 34 11 44

AMOUNT OF ACTIVITY (35)

NA

LOCATION OF RELEASE (36)

NA

45 84

PERSONNEL EXPOSURES		TYPE		DESCRIPTION	
NUMBER					
1	7	0	0	0	NA

PERSONNEL INJURIES		DESCRIPTION	
NUMBER			
0	0	0	40
		NA	

8 9		11 12		80	
LOSS OF OR DAMAGE TO FACILITY		TYPE		DESCRIPTION	
1	2	3	4	5	6
		Z	(47)	NA	

7 8 9 10
 PUBLICATION 8303210545 830301
 ISSUED DESCRIPTION (45) PDR ADOCK 05000416
 (2) (0) (N) (44) S PDR
 NRC USE ONLY
 68 69 80

NAME OF PREPARER Matthew V. Rohrer and Boyd Shingleton

PHONE