


Georgia Power Company
Post Office Box 439
Baxley, Georgia 31513
Telephone 912 367-7781
912 537-9444



Edwin I. Hatch Nuclear Plant


February 24, 1983
GM-83-146

PLANT E. I. HATCH
Licensee Event Report
Docket No. 50-366

United States Nuclear Regulatory Commission
Office of Inspection and Enforcement
Region II
Suite 3100
101 Marietta Street
Atlanta, Georgia 30303

ATTENTION: Mr. James P. O'Reilly

Pursuant to section 6.9.2 of Hatch Unit 2 Technical
Specifications, please find attached Special Report #
50-366/1983-01.


H. C. Nix
General Manager

HCN/HLS/hh

xc: R. J. Kelly
G. F. Head
J. T. Beckham, Jr.
P. D. Rice
K. M. Gillespie
S. B. Tipps
R. D. Baker
Control Room
Document Control

8303210694 830224
PDR ADOCK 05000366
S PDR

OFFICIAL COPY

TE 22

Narrative for Special Report
50-366/1983-01

On January 25, 1983, with Unit 2 in the RUN mode at 1714 MWt, the spray/sprinkler system providing protection for the Unit 2 East Cableway was isolated in order to perform modifications to the system. A continuous fire watch and a 14 day LCO were established per Technical Specifications section 3.7.6.2, ACTION a.

Technical Specifications section 3.7.6.2 ACTION a., further requires restoration of the system to operable status within 14 days or submit a Special Report to the NRC pursuant to Technical Specification section 6.9.2. The spray/sprinkler system was still out of service on February 8, 1983, thus this Special Report is required.

The spray/sprinkler system is being modified to provide protection for an area of the Unit 2 East Cableway that was previously protected by an extension of the Unit 1 spray/sprinkler system. The modification is expected to be complete by the middle of March.