




LOUISIANA
POWER & LIGHT

142 DELARONDE STREET
P. O. BOX 6008 • NEW ORLEANS, LOUISIANA 70174 • (504) 366-2345

June 15, 1983

W3I83-0211
Q-3-A35.07.79

Mr. John T. Collins, Regional Administrator, Region IV
U. S. Nuclear Regulatory Commission
611 Ryan Plaza Drive, Suite 1000
Arlington, Texas 76012



SUBJECT: Waterford SES Unit No. 3
Docket No. 50-382
Significant Construction Deficiency Report No. 79
"Unqualified Components in Hydrogen Analyzers"
Second Interim Report

Reference: LP&L Letter W3I83-0154 dated May 11, 1983

Dear Mr. Collins:

The above referenced letter indicated submittal of a Final Report to the USNRC no later than June 15, 1983.

At the present time, the qualified replacement pump motors have not yet been installed. A Final Report will be submitted to the USNRC by July 29, 1983.

Very truly yours,

F. J. Drummond
Project Support Manager - Nuclear

FJD/MAL/grf

cc: 1) Director
Office of Inspection & Enforcement
U. S. Nuclear Regulatory Commission
Washington, D. C. 20555

3) Mr. E. L. Blake

2) Director
Office of Management
Information and Program Control
U. S. Nuclear Regulatory Commission
Washington, D. C. 20555

4) Mr. W. M. Stevenson

8306270052 830615
PDR ADDCK 05000382
S PDR

IE-27

1/0