

DUKE POWER COMPANY

P.O. BOX 33189
CHARLOTTE, N.C. 28242

HAL B. TUCKER
VICE PRESIDENT
NUCLEAR PRODUCTION

TELEPHONE
(704) 373-4531

June 14, 1983


Mr. James P. O'Reilly, Regional Administrator
U. S. Nuclear Regulatory Commission
Region II
101 Marietta Street NW, Suite 2900
Atlanta, Georgia 30303

Re: McGuire Nuclear Station Unit 1
Docket No. 50-369

Dear Mr. O'Reilly:

Reportable Occurrence Report RO-369/83-35 was to have been submitted by June 14, 1983. This 30 day Reportable Occurrence (pursuant to T.S. 6.9.1.11) concerns T.S. 3.4.3, "The pressurizer shall be operable with...at least two groups of pressurizer heaters each having a capacity of at least 150 kw", which was violated on May 15, 1983. At this time investigation of the incident and preparation of a report are not yet complete. The report will be submitted by June 28, 1983.

Very truly yours,



Hal B. Tucker

PBN:jfw

cc: Document Control Desk
U. S. Nuclear Regulatory Commission
Washington, D. C. 20555

Mr. W. T. Orders
NRC Resident Inspector
McGuire Nuclear Station

Records Center
Institute of Nuclear Power Operations
1100 Circle 75 Parkway, Suite 1500
Atlanta, Georgia 30339

8306270124 830614
PDR ADDCK 05000369
S PDR

OFFICIAL COPY

IE 22
1/0

83 JUN 20 AIO: 00
USNRC REGION I
ATLANTA, GEORGIA