




**GULF STATES UTILITIES COMPANY**

POST OFFICE BOX 2951 • BEAUMONT, TEXAS 77704

AREA CODE 713 838-6631

June 17, 1983  
RBG- 15,265  
File Nos. G9.5, G9.25.1.1

Mr. John T. Collins, Regional Administrator  
U. S. Nuclear Regulatory Commission  
Region IV, Office of Inspection and Enforcement  
611 Ryan Plaza Drive, Suite 1000  
Arlington, Texas 76011




Dear Mr. Collins:

River Bend Station Unit 1  
Docket No. 50-458  
Interim Report/DR-103

On March 25, 1983, Gulf States Utilities Company (GSU) notified Region IV of a condition potentially reportable under 10CFR50.55(e) concerning linear indications found in the lifting lugs on the containment dome (DR-103). GSU is awaiting additional information from our architect-engineer. An interim or final status report will be provided by August 11, 1983.

Sincerely,

  
J. E. Booker  
Manager-Engineering,  
Nuclear Fuels & Licensing  
River Bend Nuclear Group

*PJQ*  
JEB/PJD/kt

cc: Director of Inspection & Enforcement  
U. S. Nuclear Regulatory Commission  
Washington, D. C. 20555

R. L. Brown (SRI)

IE-27

8306270156 830617  
PDR ADOCK 05000458  
S PDR

1/0