




ARKANSAS POWER & LIGHT COMPANY

Arkansas Nuclear One
P. O. Box 608
Russellville, Arkansas 72801
June 16, 1983

ANO-83-2-0405



Mr. John Collins^X
Regional Administrator
Office of Inspection and Enforcement
Region IV
U.S. Nuclear Regulatory Commission
611 Ryan Plaza Drive, Suite 1000
Arlington, Texas 76011


SUBJECT: Arkansas Nuclear One - Unit Two
Reportable Occurrence 50-368/83-025/01T-0

Dear Mr. Collins:

This facsimile is to confirm the telephone conversation between Mr. Joe Callan (NRC, Region IV) and Mr. J. M. Levine (ANO General Manager) at approximately 1530 hours on June 15, 1983.

At approximately 1330 on June 15, 1983, it was determined that since May 17, 1983 the response time of one Reactor Coolant System RTD had degraded to the point that the effective RTD time constant of Core Protection Calculator channel D T-cold had not been adequately compensated as prescribed in Technical Specification Table 3.3-3. A new penalty was calculated and entered by 1430 on June 15, 1983. This has been determined to be reportable per Technical Specification 6.9.1.8.b as required by the July 21, 1982 letter from C. M. Trammel to William Cavanaugh transmitting amendment 33 to license NPF-6. Further details will follow in a Licensee Event Report (LER) 50-368/83-025.

Sincerely,


J. M. Levine

General Manager

8306270192 830616
PDR ADOCK 05000368
S PDR

JML/MJK/cmc

cc: W. Cavanaugh, III
J. M. Griffin
J. R. Marshall
INFO
Resident NRC Inspectors
ANO-DCC

IE-29

1/0