




LOUISIANA
POWER & LIGHT

142 DELARONDE STREET
P O BOX 6008 • NEW ORLEANS, LOUISIANA 70174 • (504) 366-2345

June 15, 1983

W3I83-0196
Q-3-A35.07.78

Mr. John T. Collins, Regional Administrator, Region IV
U. S. Nuclear Regulatory Commission
611 Ryan Plaza Drive, Suite 1000
Arlington, Texas 76012



SUBJECT: Waterford SES Unit No. 3
Docket No. 50-382
Significant Construction Deficiency No. 78
"American Bridge RAB, FHB Bolting and Welding Deficiencies"
Second Interim Report

REFERENCE: LP&L letter W3I83-0144 dated April 28, 1983

Dear Mr. Collins:

The above referenced letter indicated submittal of a Final Report to the USNRC no later than June 30, 1983.

At the present time, 100% reinspection is scheduled for all American Bridge work pertaining to SCD 78 and SCD 73, "American Bridge RCB Structural Steel Welding Deficiencies". Due to the similarity and fact that these deficiencies pertain to one contractor's work (i.e., American Bridge), it has been decided to combine SCD 73 into SCD 78. Therefore, SCD 73 is closed and this response should be considered as the final Report. In addition, the new title will be "American Bridge Structural Steel Deficiencies" which hereafter will be referred to as SCD 78. This combined reinspection and rework is scheduled for completion on August 15, 1983.

Therefore, a Final Report will be submitted to the NRC by August 31, 1983.

Very truly yours,

F. J. Drummond
Project Support Manager - Nuclear

FJD/RWP/MAL:keh

- | | |
|---|--|
| cc: 1) Director
Office of Inspection & Enforcement
U. S. Nuclear Regulatory Commission
Washington, D. C. 20555 | 2) Director
Office of Management
Information and Program Control
U. S. Nuclear Regulatory Commission
Washington, D. C. 20555 |
| 3) Mr. E. L. Blake | 4) Mr. W. M. Stevenson |

8306270213 830615
PDR ADDCK 05000382
S PDR

IE-27
1/0