



Commonwealth Edison

Dresden Nuclear Power Station

R.R. #1

Morris, Illinois 60450

Telephone 815/942-2920

March 17, 1983

DJS Ltr. #83-291

James G. Keppler, Regional Administrator
Region III
U.S. Nuclear Regulatory Commission
799 Roosevelt Road
Glen Ellyn, IL 60137

Updated Reportable Occurrence Report #82-43/01X-2, Docket #050-237 is being submitted to your office in accordance with Dresden Nuclear Power Station Technical Specification 6.6.B.1.(f), personnel error or procedural inadequacy which prevents or could prevent, by itself, the fulfillment of the functional requirements of systems required to cope with accidents analyzed in the SAR. The updated report corrects the LER number on this letter and on NRC Report Form.

D. J. Scott
Station Superintendent
Dresden Nuclear Power Station

DJS/nh

Enclosure

cc/ Director of Inspection & Enforcement
Director of Management Information & Program Control
U.S. NRC, Document Management Branch
File/NRC

IE22

SUPPLEMENT TO DVR

DVR NO.	STA	UNIT.	YEAR	NO.
D - 12 - 2 - 82 - 72				

PART 1	TITLE OF EVENT	OCCURRED	
	Torus Sightglass Found Valved In And Vented	10/2/82 DATE	1700 TIME
REASON FOR SUPPLEMENTAL REPORT			
Correct LER number on cover letter and on report			
PART 2			
ACCEPTANCE BY STATION REVIEW	<i>J. Brunner</i>	<i>John M. Almon</i>	
DATE	3/17/83	3/18/83	
SUPPLEMENTAL REPORT APPROVED AND AUTHORIZED FOR DISTRIBUTION	<i>Douglas Dett</i> STATION SUPERINTENDENT	3/18/83 DATE	

MAR 21 1983