



Carolina Power & Light Company

P. O. Box 101, New Hill, North Carolina 27562  
June 16, 1983

FILE: SH N-2/18  
Item 128

MQAH 83-135

Mr. James P. O'Reilly  
United States Nuclear Regulatory Commission  
Region II  
101 Marietta Street, Northwest  
Atlanta, Georgia 30303

SHEARON HARRIS NUCLEAR POWER PLANT, UNIT 1  
DOCKET NO. 50-400  
WELDING DEFICIENCIES IN UNIT 1 EMERGENCY  
SERVICE WATER STRAINERS

Dear Mr. O'Reilly:


This is to confirm the June 16, 1983 telephone conversation between Mr. N. J. Chiangi and Mr. A. Hardin. Mr. Hardin was informed that the April 8, 1983 potentially reportable item, pertaining to weld deficiencies on two (2) ASME Section III, Class 3, emergency service water strainers supplied by R. P. Adams of Buffalo, New York, has been evaluated and considered not to be reportable per the provisions of 10CFR50.55(e) and 10CFR, Part 21.

Thank you for your consideration in this matter.

Yours very truly,

NJC/mt

cc: Mr. G. Maxwell  
Mr. V. Stello

  
N. J. Chiangi - Manager  
Quality Assurance/Quality Control  
Harris Plant

USNRC REGION II  
ATLANTA, GEORGIA  
83 JUN 22 9:34