

# LICENSEE EVENT REPORT

CONTROL BLOCK:

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

01 M I D C C 2 2 0 0 0 - 0 0 0 0 0 0 - 0 0 0 3 4 1 1 1 1 4 5  
 7 8 9 14 15 25 25 57 CAT 58

CON'T  
 01 REPORT SOURCE 1 6 0 5 0 0 0 3 1 6 7 0 2 1 8 8 3 8 0 3 1 7 8 3 9  
 7 8 60 61 68 69 74 75 80

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES 10

02 DURING THE INVESTIGATION OF AN INTRUSION ALARM AT THE ENTRANCE TO THE CD EMERGENCY  
 03 DIESEL GENERATOR ROOM, SECURITY PERSONNEL DISCOVERED THE CARDOX SYSTEM ISOLATED WITH  
 04 NO FIRE WATCH ESTABLISHED. THIS EVENT IS NON-CONSERVATIVE WITH RESPECT TO  
 05 TECHNICAL SPECIFICATION 3.7.9.3. THE PUBLIC HEALTH AND SAFETY WERE NOT AFFECTED.  
 06 PREVIOUS OCCURRENCES OF A SIMILAR NATURE INCLUDE: 315/82-037, 044, 045, 068, 081  
 07 AND 316/82-054, 076.

08 9

09 SYSTEM CODE CAUSE CODE CAUSE SUBCODE COMPONENT CODE COMP. SUBCODE VALVE SUBCODE  
 9 10 11 12 13 14 15 16  
 A B 11 A 12 X 13 I N S T R U 14 S 15 Z 16

17 LER/RO REPORT NUMBER 8 3 21 22 23 24 25 26 27 28 29 30 31 32  
 0 2 2 0 3 L 0

ACTION TAKEN 13 X 19 FUTURE ACTION 34 X 35 EFFECT ON PLANT 35 Z 20 SHUTDOWN METHOD 36 Z 21 HOURS 22 0 0 0 0 40 ATTACHMENT SUBMITTED 41 N 23 NPRD-4 FORM SUB. 42 N 24 PRIME COMP. SUPPLIER 43 N 25 COMPONENT MANUFACTURER 44 C 1 2 5 47

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS 27

10 A THOROUGH INVESTIGATION BY PLANT SECURITY PERSONNEL WAS UNABLE TO DETERMINE THE  
 11 INDIVIDUAL RESPONSIBLE FOR LEAVING THE CARDOX SYSTEM SWITCH IN THE ISOLATED POSITION.  
 12 A DESIGN CHANGE HAS BEEN INITIATED TO INSTALL KEY-LOCK SWITCHES TO PROVIDE CONTROLS  
 13 ON THE ISOLATION SWITCHES. AN ALTERNATE TO THIS CONTROL IS ALSO BEING CONSIDERED.

14 8 9

15 FACILITY STATUS 8 E 28 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60  
 1 5 E 28 1 0 0 29 NA 30 METHOD OF DISCOVERY 31 B 32 SECURITY PERSONNEL OBSERVATION

16 ACTIVITY CONTENT 8 Z 33 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60  
 1 6 Z 33 Z 34 NA 35 LOCATION OF RELEASE 36 NA

17 PERSONNEL EXPOSURES 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60  
 1 7 0 0 0 37 Z 38 NA 39

18 PERSONNEL INJURIES 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60  
 1 8 0 0 0 40 NA 41

19 LOSS OF OR DAMAGE TO FACILITY 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60  
 1 9 Z 42 NA 43

20 PUBLICITY 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60  
 2 0 N 44 NA 45

NRC USE ONLY

8303240402 830317  
 PDR ADOCK 05000316  
 S PDR

R. A. PALMER

PHONE 616/465/5901