



MISSISSIPPI POWER & LIGHT COMPANY

Helping Build Mississippi

P. O. BOX 1640, JACKSON, MISSISSIPPI 39205

March 14, 1983

JAMES P. McGAUGHY, JR.
ASSISTANT VICE PRESIDENT

Office of Inspection & Enforcement
U. S. Nuclear Regulatory Commission
Region II
101 Marietta St., N.W., Suite 2900
Atlanta, Georgia 30303

Attention: Mr. J. P. O'Reilly, Regional Administrator

Dear Mr. O'Reilly:

SUBJECT: Grand Gulf Nuclear Station
Unit 1
Docket No. 50-416
License No. NPF-13
File 0260/L-835.0
Update Report - Smoke Detector
Deficiencies
LER 82-018/01 X-1
AECM-83/0170

This letter submits an update to a previous report submitted on August 10, 1982. The event for which the report was made occurred on July 28, 1982, when a special inspection by the Fire Protection Safety Coordinator revealed a discrepancy between the FSAR and field conditions involving fire detection equipment. The event was reported pursuant to Technical Specification 6.9.1.12.1.

An evaluation has determined that no additional fire detection is needed in the Turbine Building. Attached is LER 82-018/01 X-1, which is a final report.

Yours truly,

James P. McGaughy, Jr.
FOR J. P. McGaughy, JR.

JPM:sap
Attachment

cc: (See Next Page)

8303240420 830314
PDR ADOCK 05000416
S PDR

Member Middle South Utilities System

ORIGINAL COPY

IE 22

03 MAR 22 A10:26

REGIONAL
ATLANTA, GEORGIA

MISSISSIPPI POWER & LIGHT COMPANY

AECM-83/0170

Page 2

cc: Mr. J. B. Richard (w/a)
Mr. R. B. McGehee (w/o)
Mr. T. B. Conner (w/o)
Mr. G. B. Taylor (w/o)

Mr. Richard C. DeYoung, Director (w/a)
Office of Inspection & Enforcement
U. S. Nuclear Regulatory Commission
Washington, D. C. 20555

Document Control Desk (w/a)
U. S. Nuclear Regulatory Commission
Washington, D. C. 20555