

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

CONTROL BLOCK: 1 2 3 4 5 6 (1) (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

0 1 2 3 4 5 6 7 8 9 C T M N S 2 (2) 0 0 - 0 0 0 0 0 0 - 0 0 (3) 4 1 1 1 1 1 (4) (5)

LICENSEE CODE 14 15 LICENSE NUMBER 25 26 LICENSE TYPE 30 57 CAT 58

REPORT
SOURCE

CON'T

0	1
R	

REPORT SOURCE LL(6)0|5|0|0|0|3|3|6|7|0|3|0|2|8|3|(6)0|3|1|1|8|3|(9)

DOCKET NUMBER 60 61 62 69 EVENT DATE 74 75 REPORT DATE 80

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

0 2 While in mode 3 at 532°F a liquid radwaste discharge was in progress. The recorder
0 3 associated with this discharge path RJR 9129 failed. This constitutes a violation of
0 4 E.T.S., 2.4.1.3. The unrecorded release lasted approximately 4 hrs. Similar events:
0 5 None

SYSTEM CODE M C (11)		CAUSE CODE E (12)		CAUSE SUBCODE B (13)		COMPONENT CODE I N S T R U (14)				COMP SUBCODE R (15)		VALVE SUBCODE Z (16)	
EVENT YEAR 8 3 (17)		SEQUENTIAL REPORT NO. 0 0 1 (18)		OCCURRENCE CODE 0 4 (19)		REPORT TYPE T (20)		REVISION NO. 0 (21)		ACTION TAKEN A (22)		FUTURE ACTION Z (23)	
EFFECT ON PLANT Z (24)		SHUTDOWN METHOD Z (25)		HOURS 0 0 0 0 (26)		ATTACHMENT SUBMITTED N (27)		NPRD-4 FORM SUB. Y (28)		PRIME COMP. SUPPLIER X (29)		COMPONENT MANUFACTURER L 1 3 0 (30)	

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

10 The recorder was discovered inoperable when the operator signed off the chart for
11 discharge termination. No alarms or discharge limits were exceeded. The failure was
12 caused by a stripped gear on the drive motor. The defective gear and motor were re-
13 placed. Action to prevent reoccurrence: None.

FACILITY STATUS		% POWER		OTHER STATUS		METHOD OF DISCOVERY		DISCOVERY DESCRIPTION	
1	5	G	78	0	0	0	B	31	Operator Observation
ACTIVITY CONTENT		RELEASED OF RELEASE		AMOUNT OF ACTIVITY		LOCATION OF RELEASE			
1	6	L	33	M	34	435 microcuries		Discharge Canal	
PERSONNEL EXPOSURES		NUMBER		TYPE		DESCRIPTION			
1	7	0	0	0	Z	38	NA		
PERSONNEL INJURIES		NUMBER		DESCRIPTION					
1	8	0	0	0			NA		
LOSS OF OR DAMAGE TO FACILITY		TYPE		DESCRIPTION					
1	9	Z	42			NA			
PUBLICITY ISSUED		DESCRIPTION		PDR ADOCK 05000336 S		NRC USE ONLY			
2	0	N	44						

NAME OF PREPARER Brendan J. Duffy

68 69

PHONE (203) 447-1791 X4458