



**GULF STATES UTILITIES COMPANY**

POST OFFICE BOX 2951 • BEAUMONT, TEXAS 77704

AREA CODE 713 838-6631

June 20, 1983


RBG- 15,277

File Nos. G9.5, G9.25.1.1

Mr. John T. Collins, Regional Administrator  
U. S. Nuclear Regulatory Commission  
Region IV, Office of Inspection and Enforcement  
611 Ryan Plaza Drive, Suite 1000  
Arlington, Texas 76011

Dear Mr. Collins:

River Bend Station Unit 1  
Docket No. 50-458  
Interim Report/DR-100



On February 22, 1983, Gulf States Utilities Company (GSU) notified Region IV of a condition potentially reportable under 10CFR50.55(e) concerning Category I motor control center MOV feeder breaker settings supplied to River Bend Station by Gould-Brown Boveri (DR-100). The breaker settings are larger than required. GSU has not completed its evaluation. An interim or final status report will be provided by July 13, 1983.

Sincerely,

*J E Booker*

J. E. Booker  
Manager-Engineering,  
Nuclear Fuels & Licensing  
River Bend Nuclear Group

*PJR*  
JEB/PJD/kt

cc: Director of Inspection & Enforcement  
U. S. Nuclear Regulatory Commission  
Washington, D. C. 20555

R. L. Brown (SRI)

8306280257 830620  
PDR ADOCK 05000458  
S PDR

IE-27.10