

RECEIVED  
NRC

SCE

*Southern California Edison Company*

SAN ONOFRE NUCLEAR GENERATING STATION

P.O. BOX 128

SAN CLEMENTE, CALIFORNIA 92672

1983 MAR 21 AM 11:35

REGION V

TELEPHONE  
(714) 492-7700

H. B. RAY  
STATION MANAGER

March 17, 1983

U.S. Nuclear Regulatory Commission  
Office of Inspection and Enforcement  
Region V  
1450 Maria Lane, Suite 210  
Walnut Creek, California 94596-5368

Attention: Mr. R. H. Engelken, Regional Administrator

Dear Sir:


Subject: Docket No. 50-362  
30-Day Report  
Licensee Event Report No. 83-016, Revision 1  
San Onofre Nuclear Generating Station, Unit 3

Reference: Letter, H.B. Ray (SCE) to R.H. Engelken (NRC),  
dated March 9, 1983

The enclosed Licensee Event Report (LER) for an occurrence involving Limiting Condition for Operation (LCO) 3.7.1.2 associated with the Auxiliary Feedwater (AFW) system has been revised to include results of our investigations into the cause and corrective actions for this occurrence.

If there are any questions regarding the above, please contact me.

Sincerely,



cc: A.E. Chaffee (USNRC Resident Inspector, Units 2 and 3)  
R.J. Pate (USNRC Resident Inspector, Units 2 and 3)

U.S. Nuclear Regulatory Commission  
Office of Inspection and Enforcement

U.S. Nuclear Regulatory Commission  
Office of Management Information and Program Control (MIPC)

Institute of Nuclear Power Operations (INPO)

8303290216 830317  
PDR ADDCK 05000362  
S PDR

IE-22  
83-127