

No. 3-82-26/3X-1

This LER is an updated version of LER 3-82-26/3L previously submitted on January 21, 1983. Applicable TECH. SPEC. is 3.5.c.2.

LICENSEE EVENT REPORT

CONTROL BLOCK: 1 (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

01 P A P B S 3 2 0 0 - 0 0 0 0 0 0 0 0 3 4 1 1 1 1 4 5
 7 8 9 LICENSE CODE 14 15 LICENSE NUMBER 25 26 LICENSE TYPE 30 57 CAT 58

CON'T
 01 REPORT SOURCE L 6 0 5 0 - 0 2 7 8 7 1 2 2 3 8 2 8 0 3 1 4 8 3 9
 7 8 60 61 DOCKET NUMBER 66 69 EVENT DATE 74 75 REPORT DATE 80

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES 10
 02 On December 23, 1982 the HPCI System was declared inoperable to
 03 investigate a delayed opening of the turbine stop valve upon system
 04 initiation. Surveillance testing was performed on redundant backup
 05 systems in accordance with TECH. SPEC. 4. 5. c. 2.
 06
 07
 08
 09

SYSTEM CODE CAUSE CODE CAUSE SUBCODE COMPONENT CODE COMP SUBCODE VALVE SUBCODE
 S F 11 E 12 D 13 X X X X X X 14 Z 15 Z 16
 9 10 11 12 13 18 19 20

LER/RO REPORT NUMBER 17 8 2 21 22
 ACTION TAKEN FUTURE ACTION EFFECT ON PLANT SHUTDOWN METHOD HOURS ATTACHED SUBMITTED NPD-4 FORM SUB PRIME COMP SUPPLIER COMPONENT MANUFACTURER
 A 18 E 19 Z 20 Z 21 0 0 0 0 22 N 23 Y 24 A 25 Y 0 1 1 0 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS 27
 10 Investigation revealed a corroded Yarway Model 516 ASWR steam trap
 11 which was not draining the inlet steam line properly, further
 12 complicated by a defective level switch on the drainpot. The level
 13 switch will be repaired and the steam trap was disassembled, rebuilt
 14 and returned to service.
 15
 16
 17
 18
 19
 20
 21
 22
 23
 24
 25
 26
 27
 28
 29
 30
 31
 32
 33
 34
 35
 36
 37
 38
 39
 40
 41
 42
 43
 44
 45
 46
 47

FACILITY STATUS % POWER OTHER STATUS METHOD OF DISCOVERY DISCOVERY DESCRIPTION
 E 28 0 9 0 29 N/A B 31 Surveillance Test
 7 8 9 10 11 12 13 44 45 46 80

ACTIVITY CONTENT RELEASED OF RELEASE AMOUNT OF ACTIVITY LOCATION OF RELEASE
 Z 33 Z 34 N/A
 7 8 9 10 11 44 45 80

PERSONNEL EXPOSURES NUMBER TYPE DESCRIPTION
 0 0 0 37 Z 38 N/A
 7 8 9 11 12 13 44 45 80

PERSONNEL INJURIES NUMBER DESCRIPTION
 0 0 0 40 N/A
 7 8 9 11 12 44 45 80

LOSS OF OR DAMAGE TO FACILITY TYPE DESCRIPTION
 Z 42 N/A
 7 8 9 10 44 45 80

PUBLICITY ISSUED DESCRIPTION
 N 44 N/A
 7 8 9 10 44 45 80

20 N 44 N/A
 7 8 9 10 44 45 80

8303290398 830314
 PDR ADOCK 05000278
 S PDR

PHONE: (215) 841-5020

8303290388 830314
PDR ADDCK 05000278
S PDR

M. J. Cooney

PHONE: (215) 841-5020