




LOUISIANA
POWER & LIGHT

142 DELARONDE STREET
P. O. BOX 6008 • NEW ORLEANS, LOUISIANA 70174 • (504) 366-2345

June 22, 1983

W3I83-0227
Q-3-A35.07.70

Mr. John T. Collins, Regional Administrator, Region IV
U. S. Nuclear Regulatory Commission
611 Ryan Plaza Drive, Suite 1000
Arlington, Texas 76012



SUBJECT: Waterford SES Unit No. 3
Docket No. 50-382
Significant Construction Deficiency No. 70
"GE 480-V Trip Coils Do Not Drop Out After Tripping"
Third Interim Report

REFERENCE: LP&L letter W3I83-0160 dated May 11, 1983

Dear Mr. Collins,

The above referenced letter indicated submittal of a Final Report to the USNRC no later than June 22, 1983.

At the present time, all corrective action is complete. The supporting documentation is currently under review by LP&L and Ebasco.

A Final Report will therefore be submitted to the USNRC by July 22, 1983.

Very truly yours,

Thomas F. Larrett for

F. J. Drummond
Project Support Manager - Nuclear

cc: 1) Director
Office of Inspection & Enforcement
U. S. Nuclear Regulatory Commission
Washington, D. C. 20555

3) Mr. E. L. Blake

2) Director
Office of Management
Information and Program Control
U. S. Nuclear Regulatory Commission
Washington, D. C. 20555

4) Mr. W. M. Stevenson

8306300099 830622
PDR ADCK 05000362
S PDR

LE 27
110