

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

CON'TEVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

7 8 9

17 LER/RO
REPORT
NUMBER

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)7 8 9

7	8	9
---	---	---

7 8 9

112

7 8 9

7	8	9
---	---	---

7 8 9

PHONE: 301-269-4742/4713

BALTIMORE GAS AND ELECTRIC COMPANY

P.O. BOX 1475

BALTIMORE, MARYLAND 21203

NUCLEAR POWER DEPARTMENT
CALVERT CLIFFS NUCLEAR POWER PLANT
LUSBY, MARYLAND 20657

June 16, 1983

Mr. James M. Allan
Acting Regional Administrator
U. S. Nuclear Regulatory Commission
Region 1
631 Park Avenue
King of Prussia, PA 19406


Docket No. 50-317
License No. DPR 53

Dear Mr. Allan:

In accordance with Technical Specification 6.9 please find the attached thirty day report for LER 83-26/3L.

Should you have any questions regarding this report, we would be pleased to discuss them with you.

Very truly yours,



L. B. Russell
Plant Superintendent

LBR:JWR:bsb

cc: Director, Office of Management Information
and Program Control
Messrs: A. E. Lundvall, Jr.
J. A. Tiernan

