



Northeast
Nuclear Energy

Millstone 3
50-423
TAC# M85410

MP3-18-94-614

Date: August 12, 1994

To: R. Joshi
Nuclear Licensing

From: *Sheldon I. Stricker*
Sheldon I. Stricker (x5409)
MP3 Technical Support Electrical/I&C Supervisor

Subject: NRC Request for Information Concerning NNECO's Response to NRC Bulletin
No. 90-01, Supplement 1-Loss of Fill-Oil in Rosemount Transmitters

The NRC requested that we expand our response to the subject Bulletin Response 1.f to provide what type of action or reviews will be done for those Rosemount transmitters that are excluded from the enhanced Rosemount surveillance program. The purpose of this memo is to provide the additional information requested by the NRC.

For those Rosemount transmitters excluded from the enhanced surveillance program, a normal calibration is performed every 24 months. A failure analysis is performed for those transmitters that fail their calibration to determine if any trends are established. Any Rosemount transmitters failing due to loss of oil-fill would be noted.

The above information should satisfy the NRC concerns. I understand this memo is being transmitted to the NRC for their information. If you or the NRC require any additional information, please do not hesitate to contact me.

cc:

G. Pitman
D. Gerber
F. Dacimo
R. Martin
D. Beachy
J. Follett
M. Yackoski

Memo

August 23, 1994

*Consider this document as
a signed original. Can be
made publically available.*

V. L. Ranney

| | | | |
|---------------------------------|-----------------------------|------|---------------------|
| Post-It [®] Fax Note | 7671 | Date | # of pages 3 |
| To V. L. Ranney | From Ravi Joshi | | |
| Co./Dept US NRC - PM-MP3 | Co. NU - Licensing | | |
| Phone # 301-504-3045 | Phone # 203-437-2184 | | |
| Fax # 301-504-2102 | Fax # 203-437-5901 | | |

IE39.10