

Mailing Address

Alabama Power Company
600 North 18th Street
Post Office Box 2641
Birmingham, Alabama 35291
Telephone 205 783-6081

F. L. Clayton, Jr.
Senior Vice President
Flintridge Building



Alabama Power

the southern electric system

July 8, 1983

Docket Nos. 50-348
50-364

Director, Nuclear Reactor Regulation
U. S. Nuclear Regulatory Commission
Washington, D. C. 20555

Attention: Mr. S. A. Varga


Joseph M. Farley Nuclear Plant - Units 1 and 2
Licensing Items Requesting
NRC Approval

Gentlemen:

Attached for your information is a status of all licensing items identified in Alabama Power Company's letter dated January 13, 1983. This status is provided on a monthly basis and updated to include any additional submittals requesting NRC approval.

If you have any questions, please advise.

Yours very truly,


F. L. Clayton, Jr.

FLCJr/GGY:lsh-D39

Attachment

cc: Mr. R. A. Thomas
Mr. G. F. Trowbridge
Mr. J. P. O'Reilly
Mr. E. A. Reeves
Mr. W. H. Bradford
Dr. I. L. Myers

App'l

STATUS OF LICENSING ITEMS REQUIRING
NRC APPROVAL
JULY 8, 1983

<u>ITEM</u>	<u>PROPOSED APCo SUBMITTAL DATE</u>	<u>ACTUAL APCo SUBMITTAL DATE</u>	<u>REQUESTED NRC APPROVAL DATE</u>	<u>ACTUAL NRC APPROVAL DATE</u>	<u>TAC NO.</u>	<u>REMARKS</u>
1. Movable Control Rod Assemblies for FNP 1 and 2 (T.S. 3/4.1.3)	02-22-83	03-04-83 06-03-83	07-15-83		49951 49952	Note 1
2. Charcoal Filters for FNP 1 and 2 (T.S. 4.7.7, 4.7.8 and 4.9.14)	03-01-83	03-04-83	09-01-83		49953 49954	APCo to appeal the initial NRC conclusions which are based on the proposed withdrawal of Generic Letter 83-13.
3. River Water System for FNP 1 and 2 (T.S. 3/4.7.5)	N/A	12-30-82	07-01-83	OVERDUE	49374 49375	See item 6, page 7
4. Diesel Generator Overload Test for FNP 1 and 2 (T.S. 4.8.1.1.2.c.5)	N/A	08-03-82 12-30-82 06-03-83	07-01-83 10-01-83		49374 49375	
5. BIT Reduction for FNP 1 and 2 (T.S. 3/4.5.4)	N/A	12-30-82 03-04-83	03-31-83 03-18-83	03-15-83	N/A	
6. Turbine Valve Surveillance for FNP 2 (T.S. 3/4.3.4)	N/A	10-08-82 12-10-82 01-18-83 05-31-83	12-01-82	NRC letter of 04-29-83 stated NRC position.	48973	APCo appeal meeting scheduled for July 13, 1983.

1. The 30 day Federal Register notification requirement of 10 CFR 50.92 may delay NRC approval of this item.
2. Delay of approval could precipitate a special outage.
3. Delay of approval will adversely affect the FNP 2 Refueling Outage in September 1983.
4. July 8, 1983 submittal requested approval of revised program by September 1, 1983.
5. Supplemented by two letters dated June 20, 1983 and made part of May 3, 1983 submittal by APCo letter dated June 29, 1983.
6. Delay of approval could preclude startup of each unit after refueling.

STATUS OF LICENSING ITEMS REQUIRING
NRC APPROVAL
JULY 8, 1983

<u>ITEM</u>	<u>PROPOSED APCo SUBMITTAL DATE</u>	<u>ACTUAL APCo SUBMITTAL DATE</u>	<u>REQUESTED NRC APPROVAL DATE</u>	<u>ACTUAL NRC APPROVAL DATE</u>	<u>TAC NO.</u>	<u>REMARKS</u>
7. RCS Pressure Isolation Valves for FNP 1 and 2 (T.S. 3/4.4.7.2 and 3/4.4.7.3)	N/A	08-10-82 12-23-82	07-01-83	OVERDUE	48714 48715	See item 7, page 8
8. Mechanical Snubber Functional Test Exemption for FNP 1 (T.S.4.7.9.e)	N/A	11-05-82	12-01-82	01-31-83	N/A	
9. Waste Gas Hydrogen/Oxygen Analyzer for FNP 1 and 2 (T.S. Table 4.3-9)	12-01-83		06-01-84			
10. ISI/IST Licensing Program						
a. Unit 1 Inservice Inspection (ISI) Program for ASME Code Class 1, 2 and 3 Components						
1) Relief Requests on vessel cladding examinations	N/A	04-17-81 01-10-83	09-01-83		48559	
2) Relief Requests on hydro-static test requirements	01-18-83	01-28-83	09-01-83		49547	
b. Unit 2 Inservice Inspection (ISI) Program for ASME Code Class 1, 2 and 3 Components						
1) Revision 0 Relief Requests	N/A	07-25-80 06-20-83	09-01-83		51033	Note 3
2) Relief Requests on vessel cladding examinations	N/A	01-10-83 06-20-83	09-01-83		49373	Note 3
3) Relief Request on hydro-static test requirements.	01-18-83	01-28-83 06-20-83	09-01-83		51062	Note 3

1. The 30 day Federal Register notification requirement of 10 CFR 50.92 may delay NRC approval of this item.
2. Delay of approval could precipitate a special outage.
3. Delay of approval will adversely affect the FNP 2 Refueling Outage in September 1983.
4. July 8, 1983 submittal requested approval of revised program by September 1, 1983.
5. Supplemented by two letters dated June 20, 1983 and made part of May 3, 1983 submittal by APCo letter dated June 29, 1983.
6. Delay of approval could preclude startup of each unit after refueling.

STATUS OF LICENSING ITEMS REQUIRING
NRC APPROVAL
JULY 8, 1983

<u>ITEM</u>	<u>PROPOSED APCo SUBMITTAL DATE</u>	<u>ACTUAL APCo SUBMITTAL DATE</u>	<u>REQUESTED NRC APPROVAL DATE</u>	<u>ACTUAL NRC APPROVAL DATE</u>	<u>TAC NO.</u>	<u>REMARKS</u>
c. Unit 1 Inservice Testing (IST) Program for AMSE Code Class 1, 2 and 3 Components						
1) Revision 2 Relief Requests	N/A	04-21-80	03-15-83	05-02-83	11277	Note 4
2) Revision 3 Relief Requests	N/A	07-16-81	03-15-83	05-02-83	11277	Note 4
3) Revision 4 Relief Requests	N/A	10-25-82	03-15-83	05-02-83	11277	Note 4
d. Unit 2 Inservice Testing (IST) Program for ASME Code Class 1, 2 and 3 Components						
1) Revision 0 Relief Requests	N/A	03-12-80 06-20-83	02-15-83	04-08-83	47051	Notes 3 & 4
2) Revision 1 Relief Requests	N/A	03-17-82 06-20-83	02-15-83	04-08-83	47051	Notes 3 & 4
3) Revision 2 Relief Requests	N/A	08-06-82 06-20-83	02-15-83	04-08-83	47051	Notes 3 & 4
11. Spent Fuel Pool Storage Additions for FNP 1	N/A	03-19-82	11-01-82 05-01-83	04-15-83	N/A	
12. Change 18 Month Interval to Refueling	04-01-83	04-05-83	10-01-83		51408 51409	
13. Meteorological Tower Surveillance for FNP 1 and 2 (T.S. 3/4.3.3.4)	02-01-83	01-24-83	08-01-83		51437 51438	APCo to evaluate NRC review.

1. The 30 day Federal Register notification requirement of 10 CFR 50.92 may delay NRC approval of this item.
2. Delay of approval could precipitate a special outage.
3. Delay of approval will adversely affect the FNP 2 Refueling Outage in September 1983.
4. July 8, 1983 submittal requested approval of revised program by September 1, 1983.
5. Supplemented by two letters dated June 20, 1983 and made part of May 3, 1983 submittal by APCo letter dated June 29, 1983.
6. Delay of approval could preclude startup of each unit after refueling.

STATUS OF LICENSING ITEMS REQUIRING
NRC APPROVAL
JULY 8, 1983

ITEM	PROPOSED APCo SUBMITTAL DATE	ACTUAL APCo SUBMITTAL DATE	REQUESTED NRC APPROVAL DATE	ACTUAL NRC APPROVAL DATE	TAC NO.	REMARKS
14. In-Core Thimbles for FNP 1 and 2 (T.S. 3.3.3.2)	N/A	N/A	N/A	N/A	N/A	
15. Safety Evaluations for Next Fuel Reloads:						
a. Unit 1 Upflow Modification	N/A	08-16-82	N/A	N/A	N/A	
b. Unit 1 Cycle 5	03-14-83	03-17-83	N/A	N/A	N/A	
c. Unit 2 Cycle 3 18 Month Fuel Cycle	09-01-83		N/A	N/A	N/A	
16. F delta H and Positive Moderator Temperature Coefficient	09-15-83		02-01-84			
17. Containment Spray	N/A	N/A	N/A	N/A	N/A	
18. Technical Specification Optimization Westinghouse Owners Group	N/A	N/A	N/A	N/A	N/A	
19. Safety Related Battery Changes	04-15-83	05-03-83	11-03-83		51631 51629	Supplemental information to be provided in July 1983.
20. Rod Swap Test During Low Power Physics Testing	03-01-83	03-01-83	N/A	N/A	N/A	
21. Rod Drop Timing During Low Power Physics Testing	N/A	N/A	N/A	N/A	N/A	

1. The 30 day Federal Register notification requirement of 10 CFR 50.92 may delay NRC approval of this item.
2. Delay of approval could precipitate a special outage.
3. Delay of approval will adversely affect the FNP 2 Refueling Outage in September 1983.
4. July 8, 1983 submittal requested approval of revised program by September 1, 1983.
5. Supplemented by two letters dated June 20, 1983 and made part of May 3, 1983 submittal by APCo letter dated June 29, 1983.
6. Delay of approval could preclude startup of each unit after refueling.

STATUS OF LICENSING ITEMS REQUIRING
NRC APPROVAL
JULY 8, 1983

ITEM	PROPOSED APCo SUBMITTAL DATE	ACTUAL APCo SUBMITTAL DATE	REQUESTED NRC APPROVAL DATE	ACTUAL NRC APPROVAL DATE	TAC NO.	REMARKS
22. Auto Rod Control Above 90% Power for Unit 2, Cycle 2 and Unit 1, Cycle 5	N/A	01-11-83 09-14-82	04-01-83 12-01-82	03-24-83	N/A	
23. Unit 2 Licensing Deletion Amendment Clarification Letter	01-12-83	01-07-83	N/A	N/A	N/A	
24. FSAR Update	07-01-83	07-01-83	N/A	N/A	N/A	
25. Administrative Changes						
a. Accumulator and ECCS Subsystem for FNP 1 and 2 (T.S. 4.5.1.1 (c) and 4.5.2.(a))	02-01-83	02-01-83	09-01-83		49184 49185	
b. Generic Letter 82-17 on Audit of Emergency Plan for FNP 1 and 2 (T.S. 6.5.2.8.e)	N/A	10-25-82	09-01-83		49068 49069	
c. Mechanical and Hydraulic Snubber Lists for FNP 1 (T.S. Table 3.7-4A and 3.7-4b)	06-01-83	05-27-83	09-01-83		49184	
d. Administrative Changes for FNP 1 and 2:	03-01-83	02-01-83	09-01-83		49184 49185	
1) Fire Detectors Table 3.3-12						
2) RHR Isolation 4.5.2.d.1						
3) River Water Surv 3/4.7.5						
4) Yard Fire Hydrant Table 3.7-7						
5) Service Water Battery 4.8.2.5.2(d) ⁵						
6) Organization Chart Figure 6.2-2						

1. The 30 day Federal Register notification requirement of 10 CFR 50.92 may delay NRC approval of this item.
2. Delay of approval could precipitate a special outage.
3. Delay of approval will adversely affect the FNP 2 Refueling Outage in September 1983.
4. July 8, 1983 submittal requested approval of revised program by September 1, 1983.
5. Supplemented by two letters dated June 20, 1983 and made part of May 3, 1983 submittal by APCo letter dated June 29, 1983.
6. Delay of approval could preclude startup of each unit after refueling.

STATUS OF LICENSING ITEMS REQUIRING
NRC APPROVAL
JULY 8, 1983

ITEM	PROPOSED APCo SUBMITTAL DATE	ACTUAL APCo SUBMITTAL DATE	REQUESTED NRC APPROVAL DATE	ACTUAL NRC APPROVAL DATE	TAC NO.	REMARKS
e. Unit 2 Pressurizer Sensor Table (T.S. 3.3.3.7)	03-01-83	02-01-83	09-01-83		49185	
f. Unit 1 Refueling Outage Change: Containment Vent	03-01-83	02-01-83	09-01-83		49184	
g. Turbine Building Hydraulic Snubbers for FNP 2	N/A	12-10-82	09-01-83		49287	
h. Incorporation of Licensing Requirements for FNP 2	N/A	11-24-82	09-01-83		49182	
1) FNP 2 License Condition 2.C.(17) - Containment Vent Line						
2) Mechanical Snubber List for FNP 2 (T.S. Table 3.7-4b)						
3) FNP 2 License Condition 2.C.(19)(b) - Containment Overcurrent Protection						
i. Organization Change to Offsite Management for FNP 1 and 2.	N/A	11-16-82 06-29-83	09-01-83		49184 49185	

1. The 30 day Federal Register notification requirement of 10 CFR 50.92 may delay NRC approval of this item.
2. Delay of approval could precipitate a special outage.
3. Delay of approval will adversely affect the FNP 2 Refueling Outage in September 1983.
4. July 8, 1983 submittal requested approval of revised program by September 1, 1983.
5. Supplemented by two letters dated June 20, 1983 and made part of May 3, 1983 submittal by APCo letter dated June 29, 1983.
6. Delay of approval could preclude startup of each unit after refueling.

LICENSING ITEMS REQUESTED SUBSEQUENT TO
APCo's JANUARY 13, 1983 LETTER
JULY 8, 1983

<u>ITEM</u>	<u>PROPOSED APCo SUBMITTAL DATE</u>	<u>ACTUAL APCo SUBMITTAL DATE</u>	<u>REQUESTED NRC APPROVAL DATE</u>	<u>ACTUAL NRC APPROVAL DATE</u>	<u>TAC NO.</u>	<u>REMARKS</u>
1. Administrative Changes	N/A	02-01-83	09-01-83		49184 49185	
a. Engineered Safety Actuation System Instrumentation ACTION Statement 20 Error						
b. Security Plan Audit Frequency						
c. Environmental Qualification (FNP 1)						
d. Augmented Low Power Test Program (FNP 2)						
2. Turbine Valve Surveillance One-Time Change (T.S. 3/4.3.4) for FNP 2	N/A	05-27-83 06-20-83	07-29-83 08-01-83		51473	
3. Snubber Visual Inspection One-Time Change (T.S. 3/4.7.9)	06-17-83	06-17-83 06-20-83 07-08-83	10-01-83		51891	Note 2
4. Environmental Qualification Exemption Request	N/A	05-20-83	Unit 2 2nd R.O. Unit 1 5th R.O.			Note 6
5. Multiplant Action Item B-32	N/A	04-06-83	09-01-83		49184 49185	
6. River Water System One-Time Technical Specification Change	N/A	06-20-83 06-20-83 06-29-83	08-03-83		51892 51893	Note 2 See item 3, page 1

1. The 30 day Federal Register notification requirement of 10 CFR 50.92 may delay NRC approval of this item.
2. Delay of approval could precipitate a special outage.
3. Delay of approval could adversely affect the FNP 2 Refueling Outage in September 1983.
4. July 8, 1983 submittal requested approval of revised program by September 1, 1983.
5. Supplemented by two letters dated June 20, 1983 and make part of May 3, 1983 submittal by APCo letter dated June 29, 1983.
6. Delay of approval could preclude startup of each unit after refueling.

LICENSING ITEMS REQUESTED SUBSEQUENT TO
APCo's JANUARY 13, 1983 LETTER
JULY 8, 1983

<u>ITEM</u>	<u>PROPOSED APCo SUBMITTAL DATE</u>	<u>ACTUAL APCo SUBMITTAL DATE</u>	<u>REQUESTED NRC APPROVAL DATE</u>	<u>ACTUAL NRC APPROVAL DATE</u>	<u>TAC NO.</u>	<u>REMARKS</u>
7. RCS Pressure Isolation Valve One-Time Technical Specification Change for Unit 2	N/A	06-20-83 07-08-83	08-15-83			Note 3 See item 7, page 2
8. Hydraulic Snubber List for FNP 2	60 days after startup following the Unit 2 2nd R. O.		07-01-84			

1. The 30 day Federal Register notification requirement of 10 CFR 50.92 may delay NRC approval of this item.
2. Delay of approval could precipitate a special outage.
3. Delay of approval could adversely affect the FNP 2 Refueling Outage in September 1983.
4. July 8, 1983 submittal requested approval of revised program by September 1, 1983.
5. Supplemented by two letters dated June 20, 1983 and make part of May 3, 1983 submittal by APCo letter dated June 29, 1983.
6. Delay of approval could preclude startup of each unit after refueling.