

50.55(e) Report
1983 MAR 23 PM 12:23
REGION V

Arizona Public Service Company

P.O. BOX 21666 • PHOENIX, ARIZONA 85036

March 17, 1983

ANPP-23278-RQT/BSK

U. S. Nuclear Regulatory Commission
Region V
Creskide Oaks Office Park
1450 Maria Lane - Suite 210
Walnut Creek, California 94596-5368

Attention: Mr. D. M. Sternberg, Chief
Reactor Projects Branch 1

Subject: Time Extension For Report - DER 82-61
A 50.55(e) Potentially Reportable Deficiency Relating to
Reactor Coolant Pump Diffusor-Ring Cap Screws May Fail And
Damage Pump
File: 83-019-026
D.4.33.2

Reference: (A) Telephone Conversation between J. Eckhardt and
G. Duckworth on October 21, 1982
(B) ANPP-22368, dated November 22, 1982 (Interim Report)
(C) ANPP-23026, dated February 16, 1983 (Time Extension)


Dear Sir:

The NRC was notified of a potentially reportable deficiency in
Reference (A), an Interim Report was transmitted by Reference (B), and a
Time Extension was requested by Reference (C). At that time, it was
estimated that a Final Report would be available by March 29, 1983.

Due to the extensive evaluation required, it is now expected that this
information will be finalized by May 18, 1983, when a complete report
will be submitted.

There is no change to the Interim Report at this time.

Very truly yours,



E. E. Van Brunt, Jr.
APS Vice President
Nuclear Projects Management
ANPP Project Director

EEVBJr/RQT:db

cc: See Attached Page 2

1027

U. S. Nuclear Regulatory Commission
Attention: Mr. D. M. Sternberg, Chief
Page 2

March 17, 1983
ANPP-23278-RQT/BSK

cc: Richard DeYoung, Director
Office of Inspection and Enforcement
U. S. Nuclear Regulatory Commission
Washington, D. C. 20555

T. G. Woods, Jr.
J. A. Roedel
D. B. Fasnacht
G. C. Andognini
J. R. Bynum
A. C. Rogers
B. S. Kaplan
W. E. Ide
J. Vorees
P. P. Klute/D. D. Green
A. C. Gehr
W. J. Stubblefield
W. G. Bingham
R. L. Patterson
R. W. Welcher
R. M. Grant
D. R. Hawkinson
L. E. Vorderbrueggen
G. A. Fiorelli