

TEXAS UTILITIES GENERATING COMPANY

2001 BRYAN TOWER - DALLAS, TEXAS 75201

February 8, 1983

PERRY G. BRITTAIN  
CHAIRMAN OF THE BOARD  
AND CHIEF EXECUTIVE

Log #TXX-3620  
File #10010

Mr. Richard C. DeYoung, Director  
Office of Inspection and Enforcement  
U. S. Nuclear Regulatory Commission  
Washington, D.C. 20555

Dear Mr. DeYoung:


Subject: Comanche Peak SES - Docket Nos. 50-445  
and 50-446 -- Information Relating to  
Recent Deficiencies in Quality

Thank you for your January 26, 1983, letter notifying us of potential quality assurance problems relating to the Ray Miller, Inc. case. We initiated an evaluation of this issue for CPSES upon receipt of a January 24, 1983, AIF INFOWIRE on this subject. To date, the Comanche Peak SES staff has developed and is implementing a program for resolution of this matter.

We also appreciate your review of the quality assurance requirements of the NRC regulations and the responsibility of senior industry management to accept primary responsibility for the quality and safety of nuclear power plants. We are fully aware of that responsibility and are confident that our program will identify the existence of any suspect material at CPSES.

We would appreciate your continuing to provide us with information relating to this and any similar problem.

Sincerely,

  
Perry G. Brittain

PGB/bhm

5340

8304050375 830208  
PDR ADOCK 05000445  
A PDR