




**GULF STATES UTILITIES COMPANY**

POST OFFICE BOX 2951 • BEAUMONT, TEXAS 77704

AREA CODE 713 838-6631

March 30, 1983  
RBG- 14,704  
File Nos. G9.5, G9.25.1.1

Mr. John T. Collins, Regional Administrator  
U. S. Nuclear Regulatory Commission  
Region IV, Office of Inspection and Enforcement  
611 Ryan Plaza Drive, Suite 1000  
Arlington, Texas 76011



Dear Mr. Collins:

River Bend Station Unit 1  
Docket No. 50-458  
Interim Report/DR-93

On January 14, 1983, Gulf States Utilities Company (GSU) notified Region IV of a condition potentially reportable under 10CFR50.55(e) concerning documentation and code stamping of the interconnecting piping between the Reactor Water Cleanup heat exchangers (DR-93). GSU is awaiting additional information from General Electric. An interim or final status report will be provided by May 25, 1983.

IE-27

Sincerely,

J. E. Booker  
Manager-Engineering,  
Nuclear Fuels & Licensing  
River Bend Nuclear Group

*PSD*  
JEB/PJD/kt

cc: Director of Inspection & Enforcement  
U. S. Nuclear Regulatory Commission  
Washington, D. C. 20555

R. L. Brown (SRI)

8304050457 830330  
PDR ADOCK 05000458  
S PDR