



June 9, 1976
L-76-216

Director of Nuclear Reactor Regulation
Attn: Mr. Victor Stello, Jr., Director
Division of Operating Reactors
U. S. Nuclear Regulatory Commission
Washington, D. C. 20555


Dear Mr. Stello:

TURKEY POINT UNIT 4
DOCKET NO. 50-251
INSPECTION OF SAFETY RELATED
HYDRAULIC PIPE RESTRAINTS
LOCATED OUTSIDE CONTAINMENT

The subject inspection was completed on April 21, 1976 in accordance with the continuing requirements of the Directorate of Licensing letter dated November 8, 1973.

All safety related hydraulic pipe restraints located outside containment were in satisfactory condition.

Very truly yours,


Robert E. Uhrig
Vice President

REU/MAS/ghf

cc: Mr. Norman C. Moseley
Jack R. Newman, Esquire

8304070193 760812
PDR ADCK 05000250
Q PDR

6058

COPY SENT REGION 