



January 21, 1976
L-76-41



Director of Nuclear Reactor Regulation
Attention: Mr. Victor Stello, Jr., Director
Division of Operating Reactors
U. S. Nuclear Regulatory Commission
Washington, D. C. 20555

Dear Mr. Stello:

TURKEY POINT UNIT 4
DOCKET NO. 50-251
INSPECTION OF SAFETY RELATED
HYDRAULIC PIPE RESTRAINTS
LOCATED OUTSIDE CONTAINMENT

The subject inspection was completed on January 13, 1976, in accordance with the continuing requirements of the Directorate of Licensing letter dated November 8, 1973.

All safety related hydraulic pipe restraints located inside containment were in satisfactory condition.

Very truly yours,

Robert E. Uhrig
Vice President

REU/MAS/cpc

cc: Mr. Norman C. Moseley
Jack P. Newman, Esquire

1084

8304070218 760121
PDR ADOCK 05000251
G PDR

COPY SENT REGION *IV*