



LOUISIANA
POWER & LIGHT

142 DELARONDE STREET
P O BOX 8008 • NEW ORLEANS, LOUISIANA 70174 • (504) 386-2345

March 28, 1983

L. V. MAURIN
Vice President Nuclear Operations

W3I83-0100
Q-3-A35.07.42

Mr. John T. Collins, Regional Administrator, Region IV
U. S. Nuclear Regulatory Commission
611 Ryan Plaza Drive, Suite 1000
Arlington, Texas 76012

SUBJECT: Waterford SES Unit No. 3
Docket No. 50-382
Significant Construction Deficiency No. 42
"HMA Auxiliary Relays"

IE-27

REFERENCE: LP&L letter W3I83-0049 from L. V. Maurin to John T. Collins,
dated February 14, 1983

Dear Mr. Collins:

At the present time, the corrective action cannot be completed due to delay in shipment of the required materials. A final report will, therefore, be delayed until May 27, 1983.

Very truly yours,

L. V. Maurin

LVM/MAL:keh

cc: 1) Director
Office of Inspection & Enforcement
U. S. Nuclear Regulatory Commission
Washington, D. C. 20555

3) Mr. E. L. Blake

2) Director
Office of Management
Information and Program Control
U. S. Nuclear Regulatory Commission
Washington, D. C. 20555

4) Mr. W. M. Stevenson