

9104180214 910415
PDR ADOCK 05000368
PDR

ATTACHMENT A

(CORRECTED COPY)

UNIT SHUTDOWNS AND POWER REDUCTIONS
REPORT FOR AUGUST, 1990

DOCKET NO. 50-368
UNIT NAME Two
DATE August, 1990
COMPLETED BY M. S. Whitt
TELEPHONE 501-964-3743

No.	Date	Type ¹	Duration (Hours)	Reason ²	Method of Shutting Down Reactor ³	Licensee Event Report #	System Code ⁴	Component Code ⁵	Cause & Corrective Action to Prevent Recurrence
90-05	900821	F	32.3	A	3	2-90-019	SB	PSV	The reactor was automatically tripped after the "B" Main Steam Isolation Valve (MSIV) closed due to a failure in a solenoid valve. The solenoid valve was replaced; further investigation is being conducted to determine the root cause of the failure.

¹
F: Forced
S: Scheduled

²
Reason:
A-Equipment Failure (Explain)
B-Maintenance or Test
C-Refueling
D-Regulatory Restriction
E-Operator Training &
License Examination
F-Administrative
G-Operational Error (Explain)
H-Other (Explain)

³
Method:
1-Manual
2-Manual Scram.
3-Automatic Scram.
4-Continuation
5-Load Reduction
9-Other

⁴
Exhibit G - Instructions
for Preparation of Data
Entry Sheets for Licensee
Event Report (LER) File (NUREG-
1022)
⁵
Exhibit I - Same Source