



**LOUISIANA**  
**POWER & LIGHT**

142 DELARONDE STREET  
P. O. BOX 6003 • NEW ORLEANS, LOUISIANA 70174 • (504) 366-2345

March 28, 1983

L. V. MAURIN  
Vice President Nuclear Operations

W3I83-0101  
Q-3-A35.07.55

Mr. John T. Collins, Regional Administrator, Region IV  
U. S. Nuclear Regulatory Commission  
611 Ryan Plaza Drive, Suite 1000  
Arlington, Texas 76012

SUBJECT: Waterford SES Unit No. 3  
Docket No. 50-382  
Significant Construction Deficiency No. 55  
"Hold Up and Boric Acid Make Up Tanks  
Incorrect Structural Calculations"  
Fifth Interim Report

REFERENCE: NP&L letter W3I83-0057 from L. V. Maurin to J. T. Collins  
dated February 17, 1983

Dear Mr. Collins:

At the present time, corrective action to the boric acid system cannot be completed due to inaccessibility of the system because of hot functional testing. A final report will, therefore, be delayed until May 23, 1983.

Very truly yours,

L. V. Maurin

LVM/MAL:keh

cc: 1) Director  
Office of Inspection & Enforcement  
U. S. Nuclear Regulatory Commission  
Washington, D. C. 20555

2) Director  
Office of Management  
Information and Program Control  
U. S. Nuclear Regulatory Commission  
Washington, D. C. 20555

3) Mr. E. L. Blake

4) Mr. W. M. Stevenson