

LICENSEE EVENT REPORT

CONTROL BLOCK:

1	2	3	4	5
---	---	---	---	---

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

0	1	M	I	D	C	C	1	2	0	0	-	0	0	0	0	0	-	0	0	3	4	1	1	1	1	4	5
---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---

7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80 81 82 83 84 85 86 87 88 89 90 91 92 93 94 95 96 97 98 99 100

CON'T

0	1	L	6	0	5	0	0	0	3	1	5	7	0	3	1	3	8	3	3	0	3	3	1	8	3	9
---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---

7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80 81 82 83 84 85 86 87 88 89 90 91 92 93 94 95 96 97 98 99 100

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

0 2 DURING A SURVEILLANCE TEST, PURSUANT TO TECH. SPEC. 4.6.1.3E, THE 612' ELEVATION

0 3 CONTAINMENT AIRLOCK INTERLOCK WAS FOUND INOPERABLE. THE AIRLOCK WAS DECLARED

0 4 INOPERABLE PER T.S. 3.6.1.3. THE ACTION STATEMENTS WERE MET. PUBLIC HEALTH AND

0 5 SAFETY WERE NOT AFFECTED. SIMILAR EVENTS: 050-316; 78-014/036-0, 78-066/036-0,

0 6 79-016/03L-0, 79-031/03L-0 AND FOR 050-315; 79-004/03L-0, 81-031/036-0,

0 7 81-042/03L-0, 81-031/03L-0 AND C/R 83-247.

0	3	S	A	11	E	12	B	13	P	E	N	E	T	R	14	A	15	Z	16	8	3	0	1	9	0	3	L	0	0	0	0	N	23	N	24	N	25	W	3	0	2	26
---	---	---	---	----	---	----	---	----	---	---	---	---	---	---	----	---	----	---	----	---	---	---	---	---	---	---	---	---	---	---	---	---	----	---	----	---	----	---	---	---	---	----

7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80 81 82 83 84 85 86 87 88 89 90 91 92 93 94 95 96 97 98 99 100

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

1 0 MALFUNCTION OF THE INTERLOCK WAS DUE TO A CABLE BEING OUT OF ADJUSTMENT, CAUSE OF

1 1 WHICH COULD NOT BE DETERMINED. THE CABLE WAS ADJUSTED AND INTERLOCK TESTED

1 2 SATISFACTORILY. A DESIGN MODIFICATION TO ENSURE POSITIVE INTERLOCK OF AIRLOCK DOORS

1 3 HAS BEEN APPROVED; RFC DC-12-1874.

1	5	E	28	1	0	0	29	NA	30	B	31	OPERATOR OBSERVATION	32
---	---	---	----	---	---	---	----	----	----	---	----	----------------------	----

7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80 81 82 83 84 85 86 87 88 89 90 91 92 93 94 95 96 97 98 99 100

1	6	Z	33	Z	34	NA	35	NA	36
---	---	---	----	---	----	----	----	----	----

7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80 81 82 83 84 85 86 87 88 89 90 91 92 93 94 95 96 97 98 99 100

1	7	0	0	0	37	Z	38	NA	39
---	---	---	---	---	----	---	----	----	----

7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80 81 82 83 84 85 86 87 88 89 90 91 92 93 94 95 96 97 98 99 100

1	8	0	0	0	40	N	41	N	42
---	---	---	---	---	----	---	----	---	----

7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80 81 82 83 84 85 86 87 88 89 90 91 92 93 94 95 96 97 98 99 100

1	9	Z	42	NA	43
---	---	---	----	----	----

7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80 81 82 83 84 85 86 87 88 89 90 91 92 93 94 95 96 97 98 99 100

1	9	Z	42	NA	43
---	---	---	----	----	----

7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80 81 82 83 84 85 86 87 88 89 90 91 92 93 94 95 96 97 98 99 100

2	3	N	44	NA	45
---	---	---	----	----	----

7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80 81 82 83 84 85 86 87 88 89 90 91 92 93 94 95 96 97 98 99 100

NAME OF PREPARER D. R. ROBINSON

PHONE: 616-465-5901