

3150-0011

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

0 9		R B		11	D		12	Z		13	Z Z Z Z		Z Z	14	Z		15	Z		16
7	8	9	10		11		12	13			14	15	16		17	18	19	20		
LER/RO REPORT NUMBER		EVENT YEAR			SEQUENTIAL REPORT NO.		OCCURRENCE CODE		REPORT TYPE		REVISION NO.									
17		8	3			0	3	9			0	3		L				0		
21	22	23	24	25	26	27	28	29	30	31	32									
ACTION TAKEN		FUTURE ACTION		EFFECT ON PLANT		SHUTDOWN METHOD		HOURS		ATTACHMENT SUBMITTED		NPRD-4 FORM SUB.		PRIME COMP. SUPPLIER		COMPONENT MANUFACTURER				
X	18	G	19	Z	20	Z	21	0	0	0	0	N	23	N	24	Z	25	Z	9	
33	34	35	36	37	38	39	40	41	42	43	44	45	46	47	48	49	50	51	52	

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

1 0 The special requirement (subnote "b" of Table 4.3.6-1) for testing these instru-

1 1 ments prior to a startup if not performed within the last 7 days, was not prop-

1 2 erly incorporated into plant procedures controlling plant startup. The channel

1 3 functional test requirements were met prior to the startup following this event.

1 4 The startup procedure has been revised to incorporate these tests.

80

FACILITY STATUS		% POWER	OTHER STATUS (30)	METHOD OF DISCOVERY	DISCOVERY DESCRIPTION (32)
1	5	(28)	(29)	(31)	(32)
			n/a	C	Review of Technical Specifications

ACTIVITY CONTENT
RELEASED OF RELEASE

1 6 33 34

AMOUNT OF ACTIVITY

n/a

35

LOCATION OF RELEASE

n/a

36

PERSONNEL EXPOSURES									
NUMBER		TYPE		DESCRIPTION					
1	7	0	0	0	0	37	2	38	n/a

PERSONNEL INJURIES										41
NUMBER										DESCRIPTION
1	8	0	0	0	40	n/a				

LOSS OF OR DAMAGE TO FACILITY
TYPE DESCRIPTION (43)

1 9 8 9 Z (42) 10 n/a

PUBLICATION
ISSUED DESCRIPTION (45) 2 0 N (44) n/a NRC USE ONLY

NRC USE ONLY

NAME OF PREPARED Jon T. Todd

PHONE (717) 542-2181 X3524