

CONTROL BLOCK:

--	--	--	--	--	--

 ①

0	1	O H D B S 1												2	- - - - -												3	4	1	1	1	1	4	5			
7	8	LICENSEE CODE												14	15	LICENSE NUMBER												25	26	LICENSE TYPE				30	57	CAT 58	

CL

0	1
7	8

REPORT SOURCE

L	6	0	5	0	0	0	3	4	6	7	0	1	2	7	8	3	8	0	4	0	4	8	3	9
60	61	DOCKET NUMBER					68	69	EVENT DATE					74	75	REPORT DATE					80			

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

(NP-33-83-11) At 1040 hours on 1/27/83 during the performance of the Weekly Station

03 Battery Surveillance Test ST 5084.01, it was discovered that battery 2P pilot cell 18

04 and battery 1P pilot cell 33 specific gravity was below 1.200 and also battery 1N

6 5 pilot cell 18 voltage read below 2.13. This placed the station in the action state-

ment of Technical Specification 3.8.2.4 since three of the four station battery banks

[07] could not be demonstrated as operable per surveillance requirement 4.8.2.3.2.

08 _____ 8

7 8 9 10 11 12 13 14 15 16 17 18 19 20

(17) LER/RO REPORT NUMBER: 83-
 EVENT YEAR: 21 22
 SEQUENTIAL REPORT NO.: 008
 OCCURRENCE CODE: 03
 REPORT TYPE: X
 NO.: 1

ACTION TAKEN		FUTURE ACTION		EFFECT ON PLANT		SHUTDOWN METHOD		HOURS				ATTACHMENT SUBMITTED		NPRD-4 FORM 30B		PRIME COMP. SUPPLIER		COMPONENT MANUFACTURER			
X	18	Z	19	Z	20	Z	21	0	0	0	0	Y	23	N	24	Z	25	Z	9	9	9
33		34		35		36		37				41		42		43		44			47

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

1	0	The cause of this event is that the current plant Technical Specification 4.8.2.3.2
---	---	---

111 is too stringent to accommodate the normal operating characteristics of these

1 2 batteries. Upon discovery, the batteries were placed on equalize charge. At 1405

1 2 : hours on 1/27/83, all batteries were declared operable following successful comple-

tion of ST 5084.01.

FACILITY STATUS		% POWER			OTHER STATUS	METHOD OF DISCOVERY	DISCOVERY DESCRIPTION
1	5	G	(28)	0 0 0	(29) NA	B (31)	Found during performance of ST 5084.01

ACTIVITY CONTENT
RELEASED OF RELEASE

AMOUNT OF ACTIVITY (35)

LOCATION OF RELEASE (36)

PERSONNEL EXPOSURES									
NUMBER			TYPE		DESCRIPTION (39)				
1	2	3	4	5	6	7	8	9	10
0	0	0	(37)	Z	(38)	NA			

PERSONNEL INJURIES		DESCRIPTION (41)	
NUMBER			
1	0	0	0
2	0	0	0
3	0	0	0
4	0	0	0
5	0	0	0
6	0	0	0
7	0	0	0
8	0	0	0
9	0	0	0
10	0	0	0
11	0	0	0
12	0	0	0
13	0	0	0
14	0	0	0
15	0	0	0
16	0	0	0
17	0	0	0
18	0	0	0
19	0	0	0
20	0	0	0
21	0	0	0
22	0	0	0
23	0	0	0
24	0	0	0
25	0	0	0
26	0	0	0
27	0	0	0
28	0	0	0
29	0	0	0
30	0	0	0
31	0	0	0
32	0	0	0
33	0	0	0
34	0	0	0
35	0	0	0
36	0	0	0
37	0	0	0
38	0	0	0
39	0	0	0
40	0	0	0
41	0	0	0
42	0	0	0
43	0	0	0
44	0	0	0
45	0	0	0
46	0	0	0
47	0	0	0
48	0	0	0
49	0	0	0
50	0	0	0
51	0	0	0
52	0	0	0
53	0	0	0
54	0	0	0
55	0	0	0
56	0	0	0
57	0	0	0
58	0	0	0
59	0	0	0
60	0	0	0
61	0	0	0
62	0	0	0
63	0	0	0
64	0	0	0
65	0	0	0
66	0	0	0
67	0	0	0
68	0	0	0
69	0	0	0
70	0	0	0
71	0	0	0
72	0	0	0
73	0	0	0
74	0	0	0
75	0	0	0
76	0	0	0
77	0	0	0
78	0	0	0
79	0	0	0
80	0	0	0
81	0	0	0
82	0	0	0
83	0	0	0
84	0	0	0
85	0	0	0
86	0	0	0
87	0	0	0
88	0	0	0
89	0	0	0
90	0	0	0
91	0	0	0
92	0	0	0
93	0	0	0
94	0	0	0
95	0	0	0
96	0	0	0
97	0	0	0
98	0	0	0
99	0	0	0
100	0	0	0

LOSS OF OR DAMAGE TO FACILITY		(43)
TYPE	DESCRIPTION	
[1, 2] Z (42)	NA	

PUBLICITY
 ISSUED (44) DESCRIPTION (45)
 1 N 1 NA
 S PDR
 8504120484 830404
 PDR ADCK 05000346
 NRC USE ONLY

NRC USE ONLY

DVR 83-018

NAME OF PREPARER

Ronald Uebbing

PHONE: 419-259-5000, Ext. 254