

TENNESSEE VALLEY AUTHORITY

CHATTANOOGA, TENNESSEE 37401

400 Chestnut Street Tower II

April 6, 1983

BLRD-50-438/82-20

BLRD-50-439/82-18

U.S. Nuclear Regulatory Commission

Region II

Attn: Mr. James P. O'Reilly, Regional Administrator

101 Marietta Street, NW, Suite 2900

Atlanta, Georgia 30303

Dear Mr. O'Reilly:


BELLEFONTE NUCLEAR PLANT UNITS 1 AND 2 - OMISSIONS TO AUXILIARY FEEDWATER  
PUMP DRAWINGS - BLRD-50-438/82-20, BLRD-50-439/82-18 - FIFTH INTERIM  
REPORT

The subject deficiency was initially reported to NRC-OIE Inspector  
R. V. Crlenjak on February 25, 1982 in accordance with 10 CFR 50.55(e) as  
NCR BLN BLP 8207. This was followed by our interim reports dated March 25,  
July 20, September 7, and December 14, 1982. This is our fifth interim  
report. TVA is still conducting its rigorous analysis of the turbine  
bearing cooling water piping. We expect to submit our next report by  
December 6, 1983.

If you have any questions, please get in touch with R. H. Shell at  
FTS 858-2688.

Very truly yours,

TENNESSEE VALLEY AUTHORITY

  
L. M. Mills, Manager  
Nuclear Licensing

cc: Mr. Richard C. DeYoung, Director  
Office of Inspection and Enforcement  
U.S. Nuclear Regulatory Commission  
Washington, D.C. 20555

Records Center  
Institute of Nuclear Power Operations  
1100 Circle 75 Parkway, Suite 1500  
Atlanta, Georgia 30339