



LOUISIANA
POWER & LIGHT

142 DELARONDE STREET • P.O. BOX 6008
NEW ORLEANS, LOUISIANA 70174-6008 • (504) 366-2345


April 5, 1983

L.V. MAURIN
Vice President Nuclear Operations

W3I83-0102
Q-3-A35.07.57

Mr. John T. Collins, Regional Administrator, Region IV
U.S. Nuclear Regulatory Commission
611 Ryan Plaza Drive, Suite 1000
Arlington, Texas 76012

SUBJECT: Waterford SES Unit No. 3
Docket No. 50-382
Significant Construction Deficiency No. 57
"Inadequate Instrumentation & Control
Installations & Turnover Documentation"
Third Interim Report



Dear Mr. Collins:

At the present time, the Ebasco Construction Engineering group is in the process of finalizing SCD 57 documentation. A final report will, therefore, be delayed until June 30, 1983.

Very truly yours,

L. V. Maurin

IE-27

LVM/MAL/ssd

cc: 1) Director
Office of Inspection & Enforcement
U.S. Nuclear Regulatory Commission
Washington, D.C. 20555

3) Mr. E. L. Blake

2) Director
Office of Management
Information and Program Control
U.S. Nuclear Regulatory Commission
Washington, D.C. 20555

4) Mr. W. M. Stevenson

8304150183 830405
PDR ADCK 05000382
S PDR