

LICENSEE EVENT REPORT

CONTROL BLOCK: 1 (1) (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80

0 1 2 3 4 5 6 7 8 9

REPORT SOURCE: L 6 0 5 0 0 0 3 6 2 7 0 3 2 5 8 3 8 0 4 0 4 8 3 9

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

0 2 1 A potential safety concern involving valve position indication for certain Westinghouse

0 3 2 gate valves was identified by the vendor. The valves indicate closed prior to the

0 4 3 valve disc fully isolating flow. Two such valves 2HV6227 and 2HV6229 are installed

0 5 4 in the Component Cooling Water System. The deficiency would violate the separation

0 6 5 and independence requirement of protection system trains, however, it would not have

0 7 6 prevented the system from performing its safety function. Therefore, public health

0 8 7 and safety were not affected by this event. See also LER 83-022, Unit 2.

0 9 8

SYSTEM CODE: S F 11

CAUSE CODE: B 12

CAUSE SUBCODE: A 13

COMPONENT CODE: V A L V E X 14

COMP SUBCODE: E 15

VALVE SUBCODE: D 16

EVENT YEAR: 8 3

SEQUENTIAL REPORT NO: 0 2 9

OCCURRENCE CODE: 0 1

REPORT TYPE: T

REVISION NO: 0

ACTION TAKEN: X 17

EFFECT ON PLANT: Z 18

SHUTDOWN METHOD: Z 19

HOURS: 0 0 0 0

ATTACHMENT SUBMITTED: N 20

NPR-4 FORM SUB: N 21

PRIME COMP SUPPLIER: N 22

COMPONENT MANUFACTURER: W 1 2 0 23

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

0 1 1 The cause of this event was due to a design defect. Corrective action includes

0 2 2 instruction to visually and manually check, to assure the valve is fully seated

0 3 3 using the hand wheels and verify the closed position, after each time the valve

0 4 4 is closed. A permanent modification in accordance with vendor recommendations will

0 5 5 be performed at a date to be established.

0 6 6

FACILITY STATUS: B 24

POWER: 0 0 0 25

OTHER STATUS: NA 30

METHOD OF DISCOVERY: D 31

DISCOVERY DESCRIPTION: Notification from Vendor 32

ACTIVITY CONTENT: Z 33

RELEASED: Z 34

AMOUNT OF ACTIVITY: NA 35

LOCATION OF RELEASE: NA 36

PERSONNEL EXPOSURES: 0 0 0 37

TYPE: Z 38

DESCRIPTION: NA 39

PERSONNEL INJURIES: 0 0 0 40

DESCRIPTION: NA 41

LOSS OF OR DAMAGE TO FACILITY: Z 42

DESCRIPTION: NA 43

RELEASE CITY: N 44

DESCRIPTION: NA 45

8304180416 830404
PDR ADOCK 05000361
S PDR

NRC USE ONLY

714/491-7700