

ALABAMA POWER COMPANY
NUCLEAR GENERATION DEPARTMENT

EMERGENCY OPERATIONS CENTER - FLINTRIDGE
EMERGENCY EQUIPMENT AND SUPPLIES


60-EIP-131

APPROVED:




Manager Nuclear Operations and Administration

Date 2/23/83




Manager Nuclear Engineering & Technical Support

Date 2/24/83



Manager-Safety Audit & Engineering Review

Date 2/23/83



Vice President-Nuclear Generation

Date 2/28/83

Date Issued 2/28/83

CONTROLLED COPY
COPY NO. 033
DO NOT REPRODUCE

Rev. 2

EMERGENCY OPERATIONS CENTER - FLINTRIDGE
EMERGENCY EQUIPMENT AND SUPPLIES

1.0 Purpose

The purpose of this procedure is to establish the actions to be taken to ensure the operational readiness of emergency equipment and supplies.

2.0 Scope

This procedure applies to the General Office staff of the Nuclear Generation Department.

3.0 References

3.1 Joseph M. Farley Nuclear Plant Emergency Plan

4.0 General

4.1 The Superintendent-Regulatory and Procedural Control, Flintridge Building, shall be responsible for implementing the requirements of this procedure.

4.2 An inventory list shall be posted on front of each emergency cabinet.

4.3 An inventory shall be performed:

4.3.1 annually

4.3.2 after each emergency or drill during which the cabinet is left unlocked and unattended.

4.4 This procedure applies only to equipment and supplies stored for emergency use.

5.0 Procedure

- 5.1 On the attached Equipment and Supply checklist (Table 1), initial the appropriate space after verifying the item is accounted for.
- 5.2 Sign and date the checklist and forward it to the Superintendent-Regulatory and Procedural Control Flintridge Building.
- 5.3 After reviewing the checklist the Superintendent-Regulatory and Procedural Control Flintridge Building shall insure any discrepancies found are corrected.

TABLE 1
FLINTRIDGE EMERGENCY OPERATIONS CENTER
EMERGENCY EQUIPMENT AND SUPPLIES CHECKLIST

<u>Description</u>	<u>Quantity</u>	<u>Initials</u>
- Drawings and Index	See Attachment A	
Emergency Dose Calculation Manual	1	_____
Emergency Implementation Procedures:		
FNP-O-EIP-0	1	_____
FNP-O-EIP-1	1	_____
FNP-O-EIP-2	1	_____
FNP-O-EIP-3	1	_____
FNP-O-EIP-4	1	_____
FNP-O-EIP-5	1	_____
FNP-O-EIP-6	1	_____
FNP-O-EIP-7	1	_____
FNP-O-EIP-8	1	_____
FNP-O-EIP-9	1	_____
FNP-O-EIP-10	1	_____
FNP-O-EIP-11	1	_____
FNP-O-EIP-12	1	_____
FNP-O-EIP-13	1	_____
FNP-O-EIP-14	1	_____
FNP-O-EIP-15	1	_____
FNP-O-EIP-16	1	_____
FNP-O-EIP-17	1	_____
FNP-O-EIP-18	1	_____
FNP-O-EIP-19	1	_____
FNP-O-EIP-23	1	_____
FNP-O-EIP-26	1	_____
FNP-O-EIP-27	1	_____
FNP-O-EIP-28	1	_____
FNP-O-EIP-29	1	_____
GO-EIP-101	1	_____
GO-EIP-102	1	_____
GO-EIP-111	1	_____
GO-EIP-112	1	_____
GO-EIP-113	1	_____
GO-EIP-114	1	_____
GO-EIP-115	1	_____
GO-EIP-116	1	_____
GO-EIP-117	1	_____
GO-EIP-118	1	_____
GO-EIP-119	1	_____
GO-EIP-131	1	_____

TABLE 1 - Page Two

<u>Description</u>	<u>Quantity</u>	<u>Initials</u>
Emergency Log Book	2	_____
Emergency Plan	1	_____
Annex I	1	_____
Annex II	1	_____
Annex III	1	_____
Emergency Plan Sources of Radiological Environmental Support Services	1	_____
FNP Emergency Status Board	1	_____
Health Physics Manual	1	_____
INPO - Voluntary Assistance Agreements	1	_____
INPO - Emergency Resources Manual	1	_____
Interagency Radiological Assistance Plan	1	_____
Offsite Agency Status Board	1	_____
On-Duty EOF Supervision Status Board	1	_____
Onsite Monitoring Point Map	1	_____
Plant Procedure Index	1	_____
PSASL (Rev. 6)	1	_____
Site Aerial Photo	1	_____
Southern Mutual Radiation Assistance Plan	1	_____
Technical Specifications		
Unit One	1	_____
Unit Two	1	_____
Telephone Directories		
APCo	1	_____
Birmingham Area	1	_____
Dothan Area	1	_____
Emergency Phone Directory (Flintridge EOF Use)	3	_____
Southern Company	1	_____

TABLE 1 - Page Three

<u>Description</u>	<u>Quantity</u>	<u>Initials</u>
Westinghouse Emergency Response Plan	1	_____
Writing Utensils	6	_____
Markers	1 box	_____
Chalk		_____
10 Mile EPZ Map	1	_____
50 Mile EPZ Map	1	_____

FLINTRIDGE DRAWING INDEX

170114 (Sheets 1-2)	Main Stm.
170117 (Sheets 1-4)	Condensate & Feedwater
170119 (Sheets 1-11)	Service water, River water, Circ. Water
175002 (Sheets 1-3)	Component Cooling Water System
175003 (Sheets 1-3)	Service Water System
175007	Aux. Feedwater System
175010 (Sheets 1 & 2)	Containment Cooling & Purge
175016 (Sheets 1-2)	Bechtel Standard P&ID Legend
175019	Post Accident Ctmt. Combustible Gas Control
175033 (Sheets 1 & 2)	Main & Aux. Steam
175037 (Sheets 1-3)	Rx. Coolant System
175038 (Sheets 1-3)	Safety Injection System
175039 (Sheets 1-4)	CVCS
175041	RHR
(175050-175063)	Aux. Bldg. & Containment Equip. Locations
175044	Diagram Legend for Westinghouse Drawings
175071 (Sheets 1-3)	S/G Blowdown
175073	Feedwater

ALABAMA POWER COMPANY
NUCLEAR GENERATION DEPARTMENT
GENERAL OFFICE NUCLEAR GENERATION
PROCEDURES
DOCUMENT TRANSMITTAL ACKNOWLEDGEMENT

To: Alabama Power Company
600 North 18th Street
Post Office Box 2641
Birmingham, Al 35291

Attention: Nuclear Generation Department
B300 Flintridge Building

Acknowledge the receipt of procedure/revision GO-EIP-102 Rev. 0 .
The superceded procedure was destroyed.

Comments:

Copy Number 33-42

Signature _____ Date _____

ALABAMA POWER COMPANY
NUCLEAR GENERATION DEPARTMENT
GENERAL OFFICE NUCLEAR GENERATION
PROCEDURES
DOCUMENT TRANSMITTAL ACKNOWLEDGEMENT

To: Alabama Power Company
600 North 18th Street
Post Office Box 2641
Birmingham, Al 35291

Attention: Nuclear Generation Department
B300 Flintridge Building

Acknowledge the receipt of procedure/revision GO-EIP-111 Rev. 0.
The superceded procedure was destroyed.

Comments:

Copy Number 33-42

Signature _____ Date _____

ALABAMA POWER COMPANY
NUCLEAR GENERATION DEPARTMENT
GENERAL OFFICE NUCLEAR GENERATION
PROCEDURES
DOCUMENT TRANSMITTAL ACKNOWLEDGEMENT

To: Alabama Power Company
600 North 18th Street
Post Office Box 2641
Birmingham, Al 35291

Attention: Nuclear Generation Department
B300 Flintridge Building

Acknowledge the receipt of procedure/revision GO-EIP-111 Rev. 1.
The superceded procedure was destroyed.

Comments:

Copy Number 33-42

Signature _____ Date _____

ALABAMA POWER COMPANY
NUCLEAR GENERATION DEPARTMENT
GENERAL OFFICE NUCLEAR GENERATION
PROCEDURES
DOCUMENT TRANSMITTAL ACKNOWLEDGEMENT

To: Alabama Power Company
600 North 18th Street
Post Office Box 2641
Birmingham, Al 35291

Attention: Nuclear Generation Department
B300 Flintridge Building

Acknowledge the receipt of procedure/revision GO-EIP-111 Rev. 2.
The superceded procedure was destroyed.

Comments:

Copy Number 33-42

Signature _____ Date _____

ALABAMA POWER COMPANY
NUCLEAR GENERATION DEPARTMENT
GENERAL OFFICE NUCLEAR GENERATION
PROCEDURES
DOCUMENT TRANSMITTAL ACKNOWLEDGEMENT

To: Alabama Power Company
600 North 18th Street
Post Office Box 2641
Birmingham, Al 35291

Attention: Nuclear Generation Department
B300 Flintridge Building

Acknowledge the receipt of procedure/revision GO-EIP-112 Rev. 0.
The superceded procedure was destroyed.

Comments:

Copy Number 33-42

Signature _____ Date _____

ALABAMA POWER COMPANY
NUCLEAR GENERATION DEPARTMENT
GENERAL OFFICE NUCLEAR GENERATION
PROCEDURES
DOCUMENT TRANSMITTAL ACKNOWLEDGEMENT

To: Alabama Power Company
600 North 18th Street
Post Office Box 2641
Birmingham, Al 35291

Attention: Nuclear Generation Department
B300 Flintridge Building

Acknowledge the receipt of procedure/revision GO-EIP-112 Rev. 1.
The superceded procedure was destroyed.

Comments:

Copy Number 33-42

Signature _____ Date _____

ALABAMA POWER COMPANY
NUCLEAR GENERATION DEPARTMENT
GENERAL OFFICE NUCLEAR GENERATION
PROCEDURES
DOCUMENT TRANSMITTAL ACKNOWLEDGEMENT

To: Alabama Power Company
600 North 18th Street
Post Office Box 2641
Birmingham, Al 35291

Attention: Nuclear Generation Department
B300 Flintridge Building

Acknowledge the receipt of procedure/revision GO-EIP-112 Rev. 2.
The superceded procedure was destroyed.

Comments:

Copy Number 33-42

Signature _____ Date _____

ALABAMA POWER COMPANY
NUCLEAR GENERATION DEPARTMENT
GENERAL OFFICE NUCLEAR GENERATION
PROCEDURES
DOCUMENT TRANSMITTAL ACKNOWLEDGEMENT

To: Alabama Power Company
600 North 18th Street
Post Office Box 2641
Birmingham, Al 35291

Attention: Nuclear Generation Department
B300 Flintridge Building

Acknowledge the receipt of procedure/revision GO-EIP-113 Rev. 0.
The superceded procedure was destroyed.

Comments:

Copy Number 33-42

Signature _____ Date _____

ALABAMA POWER COMPANY
NUCLEAR GENERATION DEPARTMENT
GENERAL OFFICE NUCLEAR GENERATION
PROCEDURES
DOCUMENT TRANSMITTAL ACKNOWLEDGEMENT

To: Alabama Power Company
600 North 18th Street
Post Office Box 2641
Birmingham, Al 35291

Attention: Nuclear Generation Department
B300 Flintridge Building

Acknowledge the receipt of procedure/revision GO-EIP-114 Rev. 0.
The superceded procedure was destroyed.

Comments:

Copy Number 33-42

Signature _____ Date _____

ALABAMA POWER COMPANY
NUCLEAR GENERATION DEPARTMENT
GENERAL OFFICE NUCLEAR GENERATION
PROCEDURES
DOCUMENT TRANSMITTAL ACKNOWLEDGEMENT

To: Alabama Power Company
600 North 18th Street
Post Office Box 2641
Birmingham, Al 35291

Attention: Nuclear Generation Department
B300 Flintridge Building

Acknowledge the receipt of procedure/revision GO-EIP-114 Rev. 1.
The superceded procedure was destroyed.

Comments:

Copy Number 33-42

Signature _____ Date _____

ALABAMA POWER COMPANY
NUCLEAR GENERATION DEPARTMENT
GENERAL OFFICE NUCLEAR GENERATION
PROCEDURES
DOCUMENT TRANSMITTAL ACKNOWLEDGEMENT

To: Alabama Power Company
600 North 18th Street
Post Office Box 2641
Birmingham, Al 35291

Attention: Nuclear Generation Department
B300 Flintridge Building

Acknowledge the receipt of procedure/revision GO-EIP-115 Rev. 0.
The superceded procedure was destroyed.

Comments:

Copy Number 33-42

Signature _____ Date _____

ALABAMA POWER COMPANY
NUCLEAR GENERATION DEPARTMENT
GENERAL OFFICE NUCLEAR GENERATION
PROCEDURES
DOCUMENT TRANSMITTAL ACKNOWLEDGEMENT

To: Alabama Power Company
600 North 18th Street
Post Office Box 2641
Birmingham, Al 35291

Attention: Nuclear Generation Department
B300 Flintridge Building

Acknowledge the receipt of procedure/revision GO-EIP-116 Rev. 0.
The superceded procedure was destroyed.

Comments:

Copy Number 33-42

Signature _____ Date _____

ALABAMA POWER COMPANY
NUCLEAR GENERATION DEPARTMENT
/ GENERAL OFFICE NUCLEAR GENERATION
PROCEDURES
DOCUMENT TRANSMITTAL ACKNOWLEDGEMENT

To: Alabama Power Company
600 North 18th Street
Post Office Box 2641
Birmingham, Al 35291

Attention: Nuclear Generation Department
B300 Flintridge Building

Acknowledge the receipt of procedure/revision GO-EIP-117 Rev. 0.
The superceded procedure was destroyed.

Comments:

Copy Number 33-42

Signature _____ Date _____

ALABAMA POWER COMPANY
NUCLEAR GENERATION DEPARTMENT
GENERAL OFFICE NUCLEAR GENERATION
PROCEDURES
DOCUMENT TRANSMITTAL ACKNOWLEDGEMENT

To: Alabama Power Company
600 North 18th Street
Post Office Box 2641
Birmingham, Al 35291

Attention: Nuclear Generation Department
B300 Flintridge Building

Acknowledge the receipt of procedure/revision GO-EIP-118 Rev. 0.
The superceded procedure was destroyed.

Comments:

Copy Number 33-42

Signature _____ Date _____

ALABAMA POWER COMPANY
NUCLEAR GENERATION DEPARTMENT
GENERAL OFFICE NUCLEAR GENERATION
PROCEDURES
DOCUMENT TRANSMITTAL ACKNOWLEDGEMENT

To: Alabama Power Company
600 North 18th Street
Post Office Box 2641
Birmingham, Al 35291

Attention: Nuclear Generation Department
B300 Flintridge Building

Acknowledge the receipt of procedure/revision GO-EIP-118 Rev. 1.
The superceded procedure was destroyed.

Comments:

Copy Number 33-42

Signature _____ Date _____

ALABAMA POWER COMPANY
NUCLEAR GENERATION DEPARTMENT
GENERAL OFFICE NUCLEAR GENERATION
PROCEDURES
DOCUMENT TRANSMITTAL ACKNOWLEDGEMENT

To: Alabama Power Company
600 North 18th Street
Post Office Box 2641
Birmingham, Al 35291

Attention: Nuclear Generation Department
B300 Flintridge Building

Acknowledge the receipt of procedure/revision GO-EIP-119 Rev. 0 .
The superceded procedure was destroyed.

Comments:

Copy Number 33-42

Signature _____ Date _____

ALABAMA POWER COMPANY
NUCLEAR GENERATION DEPARTMENT
GENERAL OFFICE NUCLEAR GENERATION
PROCEDURES
DOCUMENT TRANSMITTAL ACKNOWLEDGEMENT

To: Alabama Power Company
600 North 18th Street
Post Office Box 2641
Birmingham, Al 35291

Attention: Nuclear Generation Department
B300 Flintridge Building

Acknowledge the receipt of procedure/revision GO-EIP-131 Rev. 0 .
The superceded procedure was destroyed.

Comments:

Copy Number 33-42

Signature _____ Date _____

ALABAMA POWER COMPANY
NUCLEAR GENERATION DEPARTMENT
/ GENERAL OFFICE NUCLEAR GENERATION
PROCEDURES
DOCUMENT TRANSMITTAL ACKNOWLEDGEMENT

To: Alabama Power Company
600 North 18th Street
Post Office Box 2641
Birmingham, Al 35291

Attention: Nuclear Generation Department
B300 Flintridge Building

Acknowledge the receipt of procedure/revision GO-EIP-131 Rev. 1.
The superceded procedure was destroyed.

Comments:

Copy Number 33-42

Signature _____ Date _____

ALABAMA POWER COMPANY
NUCLEAR GENERATION DEPARTMENT
GENERAL OFFICE NUCLEAR GENERATION
PROCEDURES
DOCUMENT TRANSMITTAL ACKNOWLEDGEMENT

To: Alabama Power Company
600 North 18th Street
Post Office Box 2641
Birmingham, Al 35291

Attention: Nuclear Generation Department
B300 Flintridge Building

Acknowledge the receipt of procedure/revision GO-EIP-132 Rev. 0.
The superceded procedure was destroyed.

Comments:

Copy Number 33-42

Signature _____ Date _____

ALABAMA POWER COMPANY
NUCLEAR GENERATION DEPARTMENT
GENERAL OFFICE NUCLEAR GENERATION
PROCEDURES
DOCUMENT TRANSMITTAL ACKNOWLEDGEMENT

To: Alabama Power Company
600 North 18th Street
Post Office Box 2641
Birmingham, Al 35291

Attention: Nuclear Generation Department
B300 Flintridge Building

Acknowledge the receipt of procedure/revision GO-EIP-134 Rev. 0.
The superceded procedure was destroyed.

Comments:

Copy Number 33-42

Signature _____ Date _____

ALABAMA POWER COMPANY
NUCLEAR GENERATION DEPARTMENT
GENERAL OFFICE NUCLEAR GENERATION
PROCEDURES
DOCUMENT TRANSMITTAL ACKNOWLEDGEMENT

To: Alabama Power Company
600 North 18th Street
Post Office Box 2641
Birmingham, Al 35291

Attention: Nuclear Generation Department
B300 Flintridge Building

Acknowledge the receipt of procedure/revision GO-EIP-134 Rev. 1 .
The superceded procedure was destroyed.

Comments:

Copy Number 33-42

Signature _____ Date _____

ALABAMA POWER COMPANY
NUCLEAR GENERATION DEPARTMENT
GENERAL OFFICE NUCLEAR GENERATION
PROCEDURES
DOCUMENT TRANSMITTAL ACKNOWLEDGEMENT

To: Alabama Power Company
600 North 18th Street
Post Office Box 2641
Birmingham, Al 35291

Attention: Nuclear Generation Department
B300 Flintridge Building

Acknowledge the receipt of procedure/revision GO-EIP-135 Rev. 0 .
The superceded procedure was destroyed.

Comments:

Copy Number 33-42

Signature _____ Date _____

J. M. FARLEY NUCLEAR PLANT
PRODUCTION DEPARTMENT DOCUMENT CONTROL
DOCUMENT TRANSMITTAL FORM
FOR DOCUMENTS TRANSMITTED TO DIRECTOR NRR (DOCKET NOS 50-348 & 50-364)
DATE 830202

DOCUMENT NUMBER	REVISION NUMBER	COPY	DOCUMENT CATEGORY
FNP-0-EIP-009	11	41	H6.17

INSTRUCTIONS TO THE ADDRESSEE

- (1) VERIFY THE DOCUMENTS RECEIVED AGREE WITH THE ABOVE DESCRIPTION
- (2) INCORPORATE THE TRANSMITTED DOCUMENTS INTO YOUR FILES
- (3) DOCUMENTS OR PORTIONS OF DOCUMENTS WHICH ARE SUPERCEDED BY THE ABOVE MUST BE DESTROYED
- (4) SIGN IN THE SPACE BELOW INDICATING THAT YOU COMPLETED THESE INSTRUCTIONS AND RETURN THIS FORM TO THE DOCUMENT CONTROL SUPERVISOR

SIGNATURE OF ADDRESSEE

J. M. FARLEY NUCLEAR PLANT
PRODUCTION DEPARTMENT DOCUMENT CONTROL
DOCUMENT TRANSMITTAL FORM
FOR DOCUMENTS TRANSMITTED TO DIRECTOR NRR (DOCKET NOS 50-348 & 50-364)
DATE 830202

DOCUMENT NUMBER	REVISION NUMBER	COPY	DOCUMENT CATEGORY
FNP-O-EIP-009	11	38	H6. 17
FNP-O-EIP-009	11	39	H6. 17
FNP-O-EIP-009	11	40	H6. 17
FNP-O-EIP-009	11	42	H6. 17
FNP-O-EIP-009	11	43	H6. 17
FNP-O-EIP-009	11	44	H6. 17
FNP-O-EIP-009	11	45	H6. 17
FNP-O-EIP-009	11	46	H6. 17
FNP-O-EIP-009	11	47	H6. 17
FNP-O-EIP-004	10	38	H6. 17
FNP-O-EIP-004	10	39	H6. 17
FNP-O-EIP-004	10	40	H6. 17
FNP-O-EIP-004	10	41	H6. 17
FNP-O-EIP-004	10	42	H6. 17
FNP-O-EIP-004	10	43	H6. 17
FNP-O-EIP-004	10	44	H6. 17
FNP-O-EIP-004	10	45	H6. 17
FNP-O-EIP-004	10	46	H6. 17
FNP-O-EIP-004	10	47	H6. 17

INSTRUCTIONS TO THE ADDRESSEE

- (1) VERIFY THE DOCUMENTS RECEIVED AGREE WITH THE ABOVE DESCRIPTION
- (2) INCORPORATE THE TRANSMITTED DOCUMENTS INTO YOUR FILES
- (3) DOCUMENTS OR PORTIONS OF DOCUMENTS WHICH ARE SUPERCEDED BY THE ABOVE MUST BE DESTROYED
- (4) SIGN IN THE SPACE BELOW INDICATING THAT YOU COMPLETED THESE INSTRUCTIONS AND RETURN THIS FORM TO THE DOCUMENT CONTROL SUPERVISOR

J. M. FARLEY NUCLEAR PLANT
PRODUCTION DEPARTMENT DOCUMENT CONTROL
DOCUMENT TRANSMITTAL FORM
FOR DOCUMENTS TRANSMITTED TO DIRECTOR NRR (DOCKET NOS 50-348 & 50-364)
DATE 830203

DOCUMENT NUMBER	REVISION NUMBER	COPY	DOCUMENT CATEGORY
FNP-0-EIP-015	7	38	H6. 17
FNP-0-EIP-015	7	39	H6. 17
FNP-0-EIP-015	7	40	H6. 17
FNP-0-EIP-015	7	41	H6. 17
FNP-0-EIP-015	7	42	H6. 17
FNP-0-EIP-015	7	43	H6. 17
FNP-0-EIP-015	7	45	H6. 17
FNP-0-EIP-015	7	46	H6. 17
FNP-0-EIP-015	7	47	H6. 17

INSTRUCTIONS TO THE ADDRESSEE

- (1) VERIFY THE DOCUMENTS RECEIVED AGREE WITH THE ABOVE DESCRIPTION
- (2) INCORPORATE THE TRANSMITTED DOCUMENTS INTO YOUR FILES
- (3) DOCUMENTS OR PORTIONS OF DOCUMENTS WHICH ARE SUPERCEDED BY THE ABOVE MUST BE DESTROYED
- (4) SIGN IN THE SPACE BELOW INDICATING THAT YOU COMPLETED THESE INSTRUCTIONS AND RETURN THIS FORM TO THE DOCUMENT CONTROL SUPERVISOR

SIGNATURE OF ADDRESSEE

2799

J. M. FARLEY NUCLEAR PLANT
PRODUCTION DEPARTMENT DOCUMENT CONTROL
DOCUMENT TRANSMITTAL FORM
FOR DOCUMENTS TRANSMITTED TO DIRECTOR NRR (DOCKET 50-348 & 50-364)
DATE 830203

DOCUMENT NUMBER	REVISION NUMBER	COPY	DOCUMENT CATEGORY
FNP-0-EIP-015	7	44	H6. 17

INSTRUCTIONS TO THE ADDRESSEE

- (1) VERIFY THE DOCUMENTS RECEIVED AGREE WITH THE ABOVE DESCRIPTION
- (2) INCORPORATE THE TRANSMITTED DOCUMENTS INTO YOUR FILES
- (3) DOCUMENTS OR PORTIONS OF DOCUMENTS WHICH ARE SUPERCEDED BY THE ABOVE MUST BE DESTROYED.
- (4) SIGN IN THE SPACE BELOW INDICATING THAT YOU COMPLETED THESE INSTRUCTIONS AND RETURN THIS FORM TO THE DOCUMENT CONTROL SUPERVISOR

SIGNATURE OF ADDRESSEE

Director NRR (Docket Nos 50-348 & 50-364) 1-5-87

Remarks:

See attached memo

[illegible]

1. Verify the documents received agree with the above description.
2. Incorporate the transmitted documents into your files.
3. Documents or portions thereof presently in your possession which are superseded by the documents hereby transmitted must be clearly marked "VOID" or destroyed. If return of superseded documents is requested in the above "Return Requested" column, attach the superseded documents to this form prior to returning it.
4. Sign in the space below indicating that you have completed these instructions and return the routing copy of this form to the below address.

WHITE - ROUTING COPY

YELLOW - SUSPENSE COPY

Alabama Power Company
P. O. Drawer 470
Ashford, Al 36312
Attention: Document Control Supervisor

Signature Of Addressee



Date _____

3-7-83

Remarks:

Region 2 NRC

VOID procedures

[illegible]

INSTRUCTIONS TO ADDRESSEE

1. Verify the documents received agree with the above description.
 2. Incorporate the transmitted documents into your files.
 3. Documents or portions thereof presently in your possession which are superseded by the documents hereby transmitted must be clearly marked "VOID" or destroyed. If return of superseded documents is requested in the above "Return Requested" column, attach the superseded documents to this form prior to returning it.
- Sign in the space below indicating that you have completed these instructions and return the routing copy of this form to the below address.

WHITE - ROUTING COPY

Alabama Power Company
P. O. Drawer 470

YELLOW - SUSPENSE COPY

Asnford, Al 36312
Attention: Document Control Supervisor

Signature Of Addressee

Remarks:

VOID procedures

[illegible]

1. Verify the documents received agree with the above description.
2. Incorporate the transmitted documents into your files.
3. Documents or portions thereof presently in your possession which are superseded by the documents hereby transmitted must be clearly marked "VOID" or destroyed. If return of superseded documents is requested in the above "Return Requested" column, attach the superseded documents to this form prior to returning it.

Sign in the space below indicating that you have completed these instructions and return the routing copy of this form to the below-address.

WHITE - ROUTING COPY

Alabama Power Company
P. O. Drawer 470

YELLOW - SUSPENSE COPY

Asnford, AJ 38312

Attention: Document Control Supervisor

Signature Of Addressee

2941

J. M. FARLEY NUCLEAR PLANT
PRODUCTION DEPARTMENT DOCUMENT CONTROL
DOCUMENT TRANSMITTAL FORM
FOR DOCUMENTS TRANSMITTED TO DIRECTOR NRR (DOCKET NOS 50-348 & 50-364)
DATE 830208

DOCUMENT NUMBER	REVISION NUMBER	COPY	DOCUMENT CATEGORY
FNP-Q-EIP-009	11A	41	H6.17

INSTRUCTIONS TO THE ADDRESSEE

- (1) VERIFY THE DOCUMENTS RECEIVED AGREE WITH THE ABOVE DESCRIPTION
- (2) INCORPORATE THE TRANSMITTED DOCUMENTS INTO YOUR FILES
- (3) DOCUMENTS OR PORTIONS OF DOCUMENTS WHICH ARE SUPERCEDED BY THE ABOVE MUST BE DESTROYED
- (4) SIGN IN THE SPACE BELOW INDICATING THAT YOU COMPLETED THESE INSTRUCTIONS AND RETURN THIS FORM TO THE DOCUMENT CONTROL SUPERVISOR

SIGNATURE OF ADDRESSEE _____

J. M. FARLEY NUCLEAR PLANT
PRODUCTION DEPARTMENT DOCUMENT CONTROL
DOCUMENT TRANSMITTAL FORM
FOR DOCUMENTS TRANSMITTED TO REGION 2 NRC
DATE 830312

DOCUMENT NUMBER	REVISION NUMBER	COPY	DOCUMENT CATEGORY
FNP-O-EIP-008	27	63	H6.17
FNP-O-EIP-008	27	64	H6.17
FNP-O-EIP-008	27	65	H6.17

INSTRUCTIONS TO THE ADDRESSEE

- (1) VERIFY THE DOCUMENTS RECEIVED AGREE WITH THE ABOVE DESCRIPTION
- (2) INCORPORATE THE TRANSMITTED DOCUMENTS INTO YOUR FILES
- (3) DOCUMENTS OR PORTIONS OF DOCUMENTS WHICH ARE SUPERCEDED BY THE ABOVE MUST BE DESTROYED
- (4) SIGN IN THE SPACE BELOW INDICATING THAT YOU COMPLETED THESE INSTRUCTIONS AND RETURN THIS FORM TO THE DOCUMENT CONTROL SUPERVISOR

SIGNATURE OF ADDRESSEE _____

J. M. FARLEY NUCLEAR PLANT
PRODUCTION DEPARTMENT DOCUMENT CONTROL
DOCUMENT TRANSMITTAL FORM
FOR DOCUMENTS TRANSMITTED TO DIRECTOR NRR (DOCKET NOS 50-348 & 50-364)
DATE 830312

DOCUMENT NUMBER

REVISION NUMBER

COPY

DOCUMENT CATEGORY

FNP-0-EIP-008

27

59

H6.17

INSTRUCTIONS TO THE ADDRESSEE

- (1) VERIFY THE DOCUMENTS RECEIVED AGREE WITH THE ABOVE DESCRIPTION
- (2) INCORPORATE THE TRANSMITTED DOCUMENTS INTO YOUR FILES
- (3) DOCUMENTS OR PORTIONS OF DOCUMENTS WHICH ARE SUPERCEDED BY THE ABOVE MUST BE DESTROYED
- (4) SIGN IN THE SPACE BELOW INDICATING THAT YOU COMPLETED THESE INSTRUCTIONS AND RETURN THIS FORM TO THE DOCUMENT CONTROL SUPERVISOR

SIGNATURE OF ADDRESSEE

J. M. FARLEY NUCLEAR PLANT
PRODUCTION DEPARTMENT DOCUMENT CONTROL
DOCUMENT TRANSMITTAL FORM
FOR DOCUMENTS TRANSMITTED TO DIRECTOR NRR (DOCKET NOS 50-348 & 50-364)
DATE 830312

DOCUMENT NUMBER	REVISION NUMBER	COPY	DOCUMENT CATEGORY
FNP-O-EIP-008	27	53	H6. 17
FNP-O-EIP-008	27	54	H6. 17
FNP-O-EIP-008	27	55	H6. 17
FNP-O-EIP-008	27	56	H6. 17
FNP-O-EIP-008	27	57	H6. 17
FNP-O-EIP-008	27	58	H6. 17
FNP-O-EIP-008	27	60	H6. 17
FNP-O-EIP-008	27	61	H6. 17
FNP-O-EIP-008	27	62	H6. 17

INSTRUCTIONS TO THE ADDRESSEE

- (1) VERIFY DOCUMENTS RECEIVED AGREE WITH THE ABOVE DESCRIPTION
- (2) INCORPORATE THE TRANSMITTED DOCUMENTS INTO YOUR FILES
- (3) DOCUMENTS OR PORTIONS OF DOCUMENTS WHICH ARE SUPERCEDED BY THE ABOVE MUST BE DESTROYED
- (4) SIGN IN THE SPACE BELOW INDICATING THAT YOU COMPLETED THESE INSTRUCTIONS AND RETURN THIS FORM TO THE DOCUMENT CONTROL SUPERVISOR

SIGNATURE OF ADDRESSEE

J. M. FARLEY NUCLEAR PLANT
PRODUCTION DEPARTMENT DOCUMENT CONTROL
DOCUMENT TRANSMITTAL FORM
FOR DOCUMENTS TRANSMITTED TO NRC-I&E WASHINGTON
DATE 821214

DOCUMENT NUMBER	REVISION NUMBER	COPY	DOCUMENT CATEGORY
EP	7	34	H6. 67
EP	7	35	H6. 67
EP	7	36	H6. 67
EP	7	37	H6. 67
EP	7	38	H6. 67
EP	7	39	H6. 67
EP	7	40	H6. 67
EP	7	41	H6. 67
EP	7	42	H6. 67
EP	7	43	H6. 67

INSTRUCTIONS TO THE ADDRESSEE

- (1) VERIFY THE DOCUMENTS RECEIVED AGREE WITH THE ABOVE DESCRIPTION
- (2) INCORPORATE THE TRANSMITTED DOCUMENTS INTO YOUR FILES
- (3) DOCUMENTS OR PORTIONS OF DOCUMENTS WHICH ARE SUPERCEDED BY THE ABOVE MUST BE DESTROYED
- (4) SIGN IN THE SPACE BELOW INDICATING THAT YOU COMPLETED THESE INSTRUCTIONS AND RETURN THIS FORM TO THE DOCUMENT CONTROL SUPERVISOR

SIGNATURE OF ADDRESSEE _____

J. M. FARLEY NUCLEAR PLANT
PRODUCTION DEPARTMENT DOCUMENT CONTROL
DOCUMENT TRANSMITTAL FORM
FOR DOCUMENTS TRANSMITTED TO OREILLY JP
DATE 821214

DOCUMENT NUMBER

REVISION NUMBER

COPY

DOCUMENT CATEGORY

EP

7

24

H6. 67

INSTRUCTIONS TO THE ADDRESSEE

- (1) VERIFY THE DOCUMENTS RECEIVED AGREE WITH THE ABOVE DESCRIPTION
- (2) INCORPORATE THE TRANSMITTED DOCUMENTS INTO YOUR FILES
- (3) DOCUMENTS OR PORTIONS OF DOCUMENTS WHICH ARE SUPERCEDED BY THE ABOVE MUST BE DESTROYED
- (4) SIGN IN THE SPACE BELOW INDICATING THAT YOU COMPLETED THESE INSTRUCTIONS AND RETURN THIS FORM TO THE DOCUMENT CONTROL SUPERVISOR

SIGNATURE OF ADDRESSEE

J. M. FARLEY NUCLEAR PLANT
PRODUCTION DEPARTMENT DOCUMENT CONTROL
DOCUMENT TRANSMITTAL FORM
FOR DOCUMENTS TRANSMITTED TO DIRECTOR NRR (DOCKET NOS 50-348 & 50-364)
DATE 830222

DOCUMENT NUMBER	REVISION NUMBER	COPY	DOCUMENT CATEGORY
FNP-O-EIP-008	26	59	H6.17

INSTRUCTIONS TO THE ADDRESSEE

- (1) VERIFY THE DOCUMENTS RECEIVED AGREE WITH THE ABOVE DESCRIPTION
- (2) INCORPORATE THE TRANSMITTED DOCUMENTS INTO YOUR FILES
- (3) DOCUMENTS OR PORTIONS OF DOCUMENTS WHICH ARE SUPERCEDED BY THE ABOVE MUST BE DESTROYED
- (4) SIGN IN THE SPACE BELOW INDICATING THAT YOU COMPLETED THESE INSTRUCTIONS AND RETURN THIS FORM TO THE DOCUMENT CONTROL SUPERVISOR

SIGNATURE OF ADDRESSEE

J. M. FARLEY NUCLEAR PLANT
PRODUCTION DEPARTMENT DOCUMENT CONTROL
DOCUMENT TRANSMITTAL FORM
FOR DOCUMENTS TRANSMITTED TO DIRECTOR NRR (DOCKET NOS 50-348 & 50-364)
DATE 830223

DOCUMENT NUMBER	REVISION NUMBER	COPY	DOCUMENT CATEGORY
FNP-0-EIP-010	11	38	H6. 17
FNP-0-EIP-010	11	39	H6. 17
FNP-0-EIP-010	11	40	H6. 17
FNP-0-EIP-010	11	41	H6. 17
FNP-0-EIP-010	11	42	H6. 17
FNP-0-EIP-010	11	43	H6. 17
FNP-0-EIP-010	11	44	H6. 17
FNP-0-EIP-010	11	45	H6. 17
FNP-0-EIP-010	11	46	H6. 17
FNP-0-EIP-010	11	47	H6. 17

INSTRUCTIONS TO THE ADDRESSEE

- (1) VERIFY THE DOCUMENTS RECEIVED AGREE WITH THE ABOVE DESCRIPTION
- (2) INCORPORATE THE TRANSMITTED DOCUMENTS INTO YOUR FILES
- (3) DOCUMENTS OR PORTIONS OF DOCUMENTS WHICH ARE SUPERCEDED BY THE ABOVE MUST BE DESTROYED
- (4) SIGN IN THE SPACE BELOW INDICATING THAT YOU COMPLETED THESE INSTRUCTIONS AND RETURN THIS FORM TO THE DOCUMENT CONTROL SUPERVISOR

SIGNATURE OF ADDRESSEE

J. M. FARLEY NUCLEAR PLANT
PRODUCTION DEPARTMENT DOCUMENT CONTROL
DOCUMENT TRANSMITTAL FORM
FOR DOCUMENTS TRANSMITTED TO RONS 2
DATE 830228

DOCUMENT NUMBER	REVISION NUMBER	COPY	DOCUMENT CATEGORY
STS	28A	67	B6.09
STS	29	67	B6.09

INSTRUCTIONS TO THE ADDRESSEE

- (1) VERIFY THE DOCUMENTS RECEIVED AGREE WITH THE ABOVE DESCRIPTION
- (2) INCORPORATE THE TRANSMITTED DOCUMENTS INTO YOUR FILES
- (3) DOCUMENTS OR PORTIONS OF DOCUMENTS WHICH ARE SUPERCEDED BY THE ABOVE MUST BE DESTROYED
- (4) SIGN IN THE SPACE BELOW INDICATING THAT YOU COMPLETED THESE INSTRUCTIONS AND RETURN THIS FORM TO THE DOCUMENT CONTROL SUPERVISOR

SIGNATURE OF ADDRESSEE

J. M. FARLEY NUCLEAR PLANT
PRODUCTION DEPARTMENT DOCUMENT CONTROL
DOCUMENT TRANSMITTAL FORM
FOR DOCUMENTS TRANSMITTED TO DIRECTOR NRR (DOCKET NOS 50-348 & 50-364
DATE 821230

DOCUMENT NUMBER	REVISION NUMBER	COPY	DOCUMENT CATEGORY
FNP-0-EIP-007	3	43	H6.17

INSTRUCTIONS TO THE ADDRESSEE

- (1) VERIFY THE DOCUMENTS RECEIVED AGREE WITH THE ABOVE DESCRIPTION
- (2) INCORPORATE THE TRANSMITTED DOCUMENTS INTO YOUR FILES
- (3) DOCUMENTS OR PORTIONS OF DOCUMENTS WHICH ARE SUPERCEDED BY THE ABOVE MUST BE DESTROYED
- (4) SIGN IN THE SPACE BELOW INDICATING THAT YOU COMPLETED THESE INSTRUCTIONS AND RETURN THIS FORM TO THE DOCUMENT CONTROL SUPERVISOR

SIGNATURE OF ADDRESSEE _____

J. M. FARLEY NUCLEAR PLANT
PRODUCTION DEPARTMENT DOCUMENT CONTROL
DOCUMENT TRANSMITTAL FORM
FOR DOCUMENTS TRANSMITTED TO DIRECTOR NRR (DOCKET NOS 50-348 & 50-364)
DATE 821230

DOCUMENT NUMBER	REVISION NUMBER	COPY	DOCUMENT CATEGORY
FNP-O-EIP-008	25	59	H6.17

INSTRUCTIONS TO THE ADDRESSEE

- (1) VERIFY THE DOCUMENTS RECEIVED AGREE WITH THE ABOVE DESCRIPTION
- (2) INCORPORATE THE TRANSMITTED DOCUMENTS INTO YOUR FILES
- (3) DOCUMENTS OR PORTIONS OF DOCUMENTS WHICH ARE SUPERCEDED BY THE ABOVE MUST BE DESTROYED
- (4) SIGN IN THE SPACE BELOW INDICATING THAT YOU COMPLETED THESE INSTRUCTIONS AND RETURN THIS FORM TO THE DOCUMENT CONTROL SUPERVISOR

SIGNATURE OF ADDRESSEE _____

To: Director NRR (Docket Nos 50-348 & 50-364) Date: 12-30-82

Remarks:

Please file with your copy of FNP-O-EIP-8

TRANSMITTED

RETURN REQUESTED

REMARKS

TITLE AND/OR NUMBER

NO.
CPS.

REV.
NO.

COPY
NO.

NO.
CPS.

REV.
NO.

COPY
NO.

On-Call Schedule
FNP-82-1138

10 - 053 thru 062

INSTRUCTIONS TO ADDRESSEE

1. Verify the documents received agree with the above description.
2. Incorporate the transmitted documents into your files.
3. Documents or portions thereof presently in your possession which are superseded by the documents hereby transmitted must be clearly marked "VOID" or destroyed. If return of superseded documents is requested in the above "Return Requested" column, attach the superseded documents to this form prior to returning it.
4. Sign in the space below indicating that you have completed these instructions and return the routing copy of this form to the below address.

WHITE - ROUTING COPY

Alabama Power Company
P. O. Drawer 470

YELLOW - SUSPENSE COPY

Ashford, AL 36312
Attention: Document Control Supervisor

Signature Of Addressee

2940

J. M. FARLEY NUCLEAR PLANT
 PRODUCTION DEPARTMENT DOCUMENT CONTROL
 DOCUMENT TRANSMITTAL FORM
 FOR DOCUMENTS TRANSMITTED TO DIRECTOR NRR (DOCKET NOS 50-348 & 50-364)
 DATE 830208

DOCUMENT NUMBER	REVISION NUMBER	COPY	DOCUMENT CATEGORY
FNP-0-EIP-004	10A	38	H6. 17
FNP-0-EIP-004	10A	39	H6. 17
FNP-0-EIP-004	10A	40	H6. 17
FNP-0-EIP-004	10A	41	H6. 17
FNP-0-EIP-004	10A	42	H6. 17
FNP-0-EIP-004	10A	43	H6. 17
FNP-0-EIP-004	10A	44	H6. 17
FNP-0-EIP-004	10A	45	H6. 17
FNP-0-EIP-004	10A	46	H6. 17
FNP-0-EIP-004	10A	47	H6. 17
FNP-0-EIP-009	11A	38	H6. 17
FNP-0-EIP-009	11A	39	H6. 17
FNP-0-EIP-009	11A	40	H6. 17
FNP-0-EIP-009	11A	42	H6. 17
FNP-0-EIP-009	11A	43	H6. 17
FNP-0-EIP-009	11A	44	H6. 17
FNP-0-EIP-009	11A	45	H6. 17
FNP-0-EIP-009	11A	46	H6. 17
FNP-0-EIP-009	11A	47	H6. 17

(2) INCORPORATE THE TRANSMITTED DOCUMENTS INTO YOUR FILES

(3) DOCUMENTS OR PORTIONS OF DOCUMENTS WHICH ARE SUPERCEDED BY THE ABOVE MUST BE DESTROY

(4) SIGN IN THE SPACE BELOW INDICATING THAT YOU COMPLETED THESE INSTRUCTIONS AND RETURN THIS FORM TO THE DOCUMENT CONTROL SUPERVISOR

SIGNATURE OF ADDRESSEE

J. M. FARLEY NUCLEAR PLANT
PRODUCTION DEPARTMENT DOCUMENT CONTROL
DOCUMENT TRANSMITTAL FORM
FOR DOCUMENTS TRANSMITTED TO DIRECTOR NRR (DOCKET NOS 50-348 & 50-364)
DATE 830222

DOCUMENT NUMBER	REVISION NUMBER	COPY	DOCUMENT CATEGORY
FNP-O-EIP-011	7	38	H6. 17
FNP-O-EIP-011	7	39	H6. 17
FNP-O-EIP-011	7	40	H6. 17
FNP-O-EIP-011	7	41	H6. 17
FNP-O-EIP-011	7	42	H6. 17
FNP-O-EIP-011	7	43	H6. 17
FNP-O-EIP-011	7	44	H6. 17
FNP-O-EIP-011	7	45	H6. 17
FNP-O-EIP-011	7	46	H6. 17
FNP-O-EIP-011	7	47	H6. 17
FNP-O-EIP-008	26	53	H6. 17
FNP-O-EIP-008	26	54	H6. 17
FNP-O-EIP-008	26	55	H6. 17
FNP-O-EIP-008	26	56	H6. 17
FNP-O-EIP-008	26	57	H6. 17
FNP-O-EIP-008	26	58	H6. 17
FNP-O-EIP-008	26	60	H6. 17
FNP-O-EIP-008	26	61	H6. 17
FNP-O-EIP-008	26	62	H6. 17

INSTRUCTIONS TO THE ADDRESSEE

- (1) VERIFY THE DOCUMENTS RECEIVED AGREE WITH THE ABOVE DESCRIPTION
- (2) INCORPORATE THE TRANSMITTED DOCUMENTS INTO YOUR FILES
- (3) DOCUMENTS OR PORTIONS OF DOCUMENTS WHICH ARE SUPERCEDED BY THE ABOVE MUST BE DESTROYED
- (4) SIGN IN THE SPACE BELOW INDICATING THAT YOU COMPLETED THESE INSTRUCTIONS AND RETURN THIS FORM TO THE DOCUMENT CONTROL SUPERVISOR

SIGNATURE OF ADDRESSEE
