




ARKANSAS POWER & LIGHT COMPANY

Arkansas Nuclear One
P. O. Box 608
Russellville, Arkansas 72801
April 11, 1983



ANO-83-2-0278

Mr. John Collins
Regional Administrator
Office of Inspection & Enforcement
Region IV
U.S. Nuclear Regulatory Commission
611 Ryan Plaza Drive, Suite 1000
Arlington, TX 76011

SUBJECT: Arkansas Nuclear One - Unit 2
Reportable Occurrence 50-368/83-014/01T-0


IE-29

Mr. Collins:

This fascimile is to confirm the telephone conversation between Mr. Bill Johnson (NRC, Region IV) and Mr. J. M. Levine (ANO General Manager) at approximately 1550 hours on April 11, 1983.

At approximately 1545 on April 11, 1983, it was determined that the response times of two Reactor Coolant System RTD's had degraded to the point that the effective RTD time constant of Core Protection Calculator Channel A T-hot input was not adequately compensated by the installed penalty factors as prescribed in Technical Specification Figure 3.3-1. New penalty factors were calculated and entered into the affected CPC by 1625 on April 11. This has been determined to be reportable per Technical Specification 6.9.1.8.b as required by the July 21, 1982 letter from C. M. Trammel to William Cavanaugh transmitting amendment 33 to license NPF-6. Further details will follow in a Licensee Event Report (LER) 50-368/83-014/01T-0. This occurrence is similar to LER 50-368/81-017/01T, 50-368/82-001/01T-0 and 50-368/83-009/01T-0.

Sincerely,


J. M. Levine
General Manager

8304190065 830411
PDR ADOCK 05000368
S PDR

JML:LJD:sbp

cc: W. Cavanaugh, III
J. M. Griffin
J. R. Marshall
INPO
Resident NRC Inspectors
ANO-DCC

MEMBER MIDDLE SOUTH UTILITIES SYSTEM