



Carolina Power & Light Company

H. B. ROBINSON STEAM ELECTRIC PLANT  
POST OFFICE BOX 790  
HARTSVILLE, SOUTH CAROLINA 29550

APR 11 1983

Robinson File No: 13510C

Serial: RSEP/83-465

Mr. James P. O'Reilly  
Regional Administrator  
U. S. Nuclear Regulatory Commission  
Region II  
101 Marietta Street, Suite 3100  
Atlanta, Georgia 30303

H. B. ROBINSON STEAM ELECTRIC PLANT, UNIT NO. 2  
DOCKET NO. 50-261  
LICENSE NO. DPR-23  
PROMPT NOTIFICATION - HVH COOLER LEAK

Dear Mr. O'Reilly:

In accordance with Plant Technical Specification 6.9.2.a.3, the following event is reported.

At 1445 hours on April 10, 1982, a service water leak was discovered on Containment Fan Cooler HVH-3. The service water to the cooler was isolated immediately. In accordance with Technical Specification 3.3.2.2.a, operability testing of the containment spray pumps was completed at 1630 hours. This event is considered a degradation of a containment boundary pursuant to IE Bulletin 80-24 and is reported as such.

This event was reported on April 11, 1983, to the NRC, Region II and the office of Mr. B. J. Furr, Vice President, Nuclear Operations Department, Carolina Power and Light Company.

Very truly yours,

for R. B. Starkey, Jr.  
General Manager  
H. B. Robinson S. E. Plant

HTC/th

cc: B. J. Furr  
S. P. Weise

8304190111 830411  
PDR ADOCK 05000261  
S PDR

OFFICIAL COPY

IE 22